

SWEDISH AIRWORTHINESS DIRECTIVES (SAD)

SAD No. 1-016 Rev B Cancels Rev A

(2) F. C. Communication of the Communication of

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE No:

1-016 Rev B

AIRCRAFT TYPE:

SAAB SF340A (SAAB-FAIRCHILD 340A)

SERIAL No:s AFFECTED:

340A-004 through -078, except aircraft with mod No 1422 incorp-

orated (Mod 1422 ref SB 33-016).

S/N 340A-014, -022, -029, -036, and -050 (corporate models) are

also excluded.

SUBJECT:

Cabin Fluorescent Lighting System

BACKGROUND:

Faulty lamps in the original cabin fluorescent lighting system leads to increased voltage and possible electromagnetic interference with other systems. SAAB-SCANIA AB has therefore designed a new system available for retrofit as mod 1422, SB SF340-33-016. This system is installed in all aircraft S/N 340A-79 and up.

To maintain continued airworthiness for aircraft that are not modified, LFV has determined that a modification of inverters that may have bad solder connections is necessary. In addition a daily inspection is required also after this inverter modification.

ACTIONS:

- A) Deactivate the WINDOW AND OVERHEAD lights by pulling and securing cb's F24 and F25.
- Modify inverter assembly P/N 18-994, S/N 650-1992 and P/N 18-996, S/N 1100-3420, in accordance with SB SF340-33-021.
- Inspect the cabin fluorescent lighting system (overhead and window lights) to ensure that all lamps are lit. If a lamp is not lit, it must be corrected prior to flight or the circuit breaker for that part of the system must be opened.

REFERENCE:

SAAB SF340A Service Bulletin SF340-33-021

COMPLIANCE TIME:

- Applies immediately upon receipt of this SAD until action B) is performed.
- Before October 1, 1987. B)
- Prior to the first flight of the day when Action B) is performed.

DATE OF ISSUE:

1987-06-18

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.

LFS 1987:15

Mail address S-601 79 NORRKÖPING Office address

Telephone No

Nat 011 - 19 20 00

Cable address

Telex address

Int +46 11 - 19 20 00

Civilair Norrköping

64250