
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-045

AIRCRAFT TYPE: SAAB SF340 and SAAB 340B

SERIAL No:s

AFFECTED: SAAB SF340A-004 through -159
SAAB 340B-160 through -169, -171 through -219

SUBJECT: Change of circuit breaker in aircraft with fwd or aft lavatory.

BACKGROUND: To prevent a possible wire-overload, if a failure occurs in the electrical system for the fwd or aft lavatory.

REFERENCE

DOCUMENTS: SAAB-SCANIA AB Service Bulletin SAAB 340-25-181.
Dated March 7, 1991.

ACTIONS: Perform actions described in SAAB-SCANIA AB Service Bulletin SAAB 340-25-181, dated March 7, 1991 or later revision.

COMPLIANCE

TIME: To be performed before September 8, 1991.

Norrköping 1991-03-20

LUFTFARTSVERKET
Flight Safety Department

LFS 1991:7

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.