

## SWEDISH AIRWORTHINESS DIRECTIVES (SAD)

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS					
DIRECTIVE NO:	1-135R1				
AIRCRAFT TYPE:	SAAB SF 340A and SAAB 340B				
SERIAL No:s AFFECTED:	SAAB SF 340A -004 through -159 SAAB 340B -160 through -453 For A/C SAAB SF340A -004 through -159 and A/C SAAB 340B -160 through -430 and -433; This SAD is valid only if any engine forward bottom mounts/canister is replaced, after January 1, 1998. Note: Effectivity changed				
SUBJECT:	Power Plant - Mounts - Inspection of the engine mounts and replacement if necessary				
BACKGROUND:	It has been found that the elastomeric material in certain bottom forward engine mounts after a short time in service has degraded. This degrading will reduce the redundancy and change the stiffness and damping characteristics of the engine support system, causing heavy chafing on the nacelle structure and chafe on the fire sensor loop. Heavy chafing of the structure may reduce its integrity and fire shielding capability and chafing of the fire sensor loop may ultimately cause a nuisance fire warning leading to a precautionary engine shut down.				
	This SAD calls out an inspection to locate degraded engine mounts and replacement if necessary.				
REFERENCE DOCUMENTS:	Saab Aircraft AB Mandatory Service Bulletin SAAB 340-71-057 revision 1, dated 18 December 1998, and its attachment 1.				
ACTIONS:	Perform actions described in Saab Aircraft AB Mandatory Service Bulletin SAAB 340-71-057 revision 1, dated 18 December, 1998, and its attachment 1, or later revision				
COMPLIANCE TIME:	To be performed within 400 flight hours. Repeated inspection after 250 flight hours, if applicable (Ref. para. 2.B. (6)) in Saab Aircraft AB Mandatory Service Bulletin SAAB 340-71-057 revision 1, dated 18 December 1998, and its attachment 1,or later revision.				
EFFECTIVE DATE:	18 December, 1998				
LUFTFARTSVERKET					

## Aviation Safety Department

## LFS 1998:86

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

Mail address	Office address	Telephone No		Cable address	Telex address
		Nat 0	11 19 20 00	Civilair	64250
SE-601 79 NORRKÖPING	Vikboplan 11	Int +46	11-19 20 00	Norrköping	
SWEDEN		Fax +46	11 19 25 15		
		+46	11 19 25 75		