



EASA Safety Information Bulletin

SIB No.: 2014-12
Issued: 06 May 2014

- Subject:** **Non-conforming Standard Hardware**
- Ref. Publication:** Federal Aviation Administration (FAA) Special Airworthiness Information Bulletin (SAIB) [HQ-14-16](#) dated 28 April 2014.
- Applicability:** Manufacturers, owners, operators, and maintenance personnel of aircraft, engines, propellers, parts and appliances.
- Description:** Prompted by [EASA SIB 2012-06R2](#), the FAA issued the referenced SAIB, addressing the same subject, but providing more detailed information on potentially non-conforming Military Specifications (MS), Army Navy Standards (AN) and National Aerospace Standards (NAS) fasteners.
- After reviewing the available information and recognising that the FAA may not be the 'State of Design' authority for all the affected fasteners, EASA concurs with the SAIB and the recommendations contained therein.
- This SIB is published to ensure that all affected persons who may have purchased any affected fasteners, and/or installed these on aircraft, engines, propellers, parts or appliances being in civil aviation service in an EASA Member State, are aware of these recommendations.
- Recommendation(s):** See referenced FAA SAIB.
- Contact(s):** For further information contact the Safety Information Section, Executive Directorate, EASA. E-mail: ADs@easa.europa.eu.

This is information only. Recommendations are not mandatory.