


EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No: 2004-6339R1 (Ref. NAA AD No. D-2004-303R1)</p> <p>Date: 21 April 2006</p>
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.	
Type Approval Holder's Name : AQUILA GmbH	Type/Model designation(s) : AQUILA AT01
TCDS Number : LBA Germany TCDS 1106	
Foreign AD : N/A	
Supersedure : LBA AD D-2004-303	
ATA 57	Wings - Bonding Defects between Wing Shell and Wing Spar
<p style="text-align: center;">Cancellation Notice</p> <p>This AD 2004-6339R1 cancels LBA AD D-2004-303 approved by EASA with ref. No. 2004-6339 on 15 June 2004.</p> <p>Applicability: AQUILA AT01 all S/N</p> <p>Reason: No further bonding defects were found in repeated checks according AD-No. D-2004-303 (Aquila Service Bulletin No. AT01-002 Issue 1). The inspection defined in AD-No. D-2004-303 was transferred to the Maintenance Manual, chapter 05-20 as scheduled annual check.</p> <p>All necessary actions must be performed on the basis of the referenced manufacturer's Service Bulletin. The AD may be cancelled.</p>	