

# Airworthiness Directive D-2004-300

## Luftfahrt-Bundesamt

Airworthiness Directive Section Hermann-Blenk-Str. 26 38108 Braunschweig Federal Republic of Germany

Effective Date: June 15, 2004

## **DG-Flugzeugbau**

**Affected:** 

Kind of aeronautical product: Sailplane

Manufacturer: DG Flugzeugbau, Bruchsal, Germany

Type: DG-1000S Models affected: DG-1000S

Serial numbers affected: all German Type Certificate No.: 413

## Subject:

Elevator – assembly of the horizontal tailplane and Manual revision

#### Reason:

A user succeeded in assembling the horizontal tailplane without connecting the elevator. A deflector has therefore been designed to prevent false assembly.

#### Action

Install a deflector and exchange pages into the Flight- and Mainentance Manual in accordance with the instructions given in the Service Bulletin.

## Compliance:

The actions must be performed not later than December 31, 2004.

## **Technical publication of the manufacturer:**

DG Flugzeugbau Technical Note No. 413/3 dated April 28, 2004 which becomes herewith part of this AD can be obtained from Messrs.:

DG-Flugzeugbau
Postbox 41 20
D- 76625 Bruchsal
Federal Republic of Germany
Phone: ++ 49 7257 890 Fax: ++ 49 7257 8922
www.dg-flugzeugbau.de

### Holders of affected aircraft registered in Germany have to observe the following:

Action has to be accomplished by the owner of the aircraft or an approved service station and to be checked and entered in the log book by a licensed inspector.

As a result of the a.m. deficiencies, the airworthiness of the aircraft is affected to such an extent that after the expiry of the a.m. dates the aircraft may be operated only after proper accomplishment of the prescribed actions. In the interest of aviation safety outweighing the interest of the receiver in a postponement of the prescribed actions, the immediate compliance with this AD is to be directed.

An appeal to this notice may be raised within a period of one month following notification. Appeals are to be raised with the Luftfahrt-Bundesamt, Hermann-Blenk-Str. 26, 38108 Braunschweig, in writing or for the purpose of drawing up minutes.

## **EASA-Approval**

Approved by EASA under Approval-No. 2004-6382 on June 15, 2004.

Enquiries regarding this Airworthiness Directive should be referred to Mr. Olaf Schneider, Airworthiness Directive Section at the above address, fax-no. 0049 531/2355-720. Please note, that in case of any difficulty, reference should be made to the German issue!