


| | | |
|--|---|-----------------------------------|
| EASA | AIRWORTHINESS DIRECTIVE CANCELLATION NOTICE | |
|  | <p style="text-align: center;">AD No.: 2006-0092R1</p> <p style="text-align: center;">Date: 16 January 2007</p> | |
| No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry. | | |
| Type Approval Holder's Name: | | Type/Model designation(s): |
| Hartzell Propeller Inc. | | Model ()HC-()2Y()-() series |
| TCDS Numbers: FAA P-920, P9EA, P27EA, P42GL, P37EA, P39EA and P43GL. | | |
| Foreign AD: FAA AD 2006-18-15, issued September 8, 2006. | | |
| Cancellation/Supersedure: This Notice cancels EASA AD 2006-0092 dated 03 May 2006, including the 'correction' dated 07 September 2006. | | |
| | | |
| ATA 61 | Propellers – Propeller Hub – Inspection | |
| | | |
| Manufacturer: | Hartzell Propeller Inc. | |
| Applicability: | <p>Hartzell two blade, aluminum hub, "compact" ()HC-()2Y()-() series propellers manufactured before December 1991 that do not have an "A" or "B" suffix letter at the end of the hub and propeller serial numbers and are installed on Lycoming ()-360 series engines.</p> <p>These engines and propellers could be installed on, but not limited to, various Part (CS) 23 certificated aircraft.</p> | |
| Reason: | <p>The Agency has reviewed the referenced FAA Airworthiness Directive 2006-18-15 that addresses the same unsafe condition that was addressed by the original issue of this directive. The actions required by the FAA AD are almost identical to the ones required by EASA AD 2006-0092. They are adequate to correct the unsafe condition and therefore that AD is considered 'accepted' under the provisions of Executive Decision (ED) No. 02/2003.</p> <p>For the reasons described above, EASA AD 2006-0092 is hereby cancelled.</p> | |
| Effective Date: | 16 January 2007 | |
| Compliance | Not applicable | |
| Ref. Publications: | Hartzell Propeller Inc. Service Bulletin HC-SB-61-269, dated April 18, 2005 | |

| | |
|----------|---|
| Remarks: | <ol style="list-style-type: none"><li data-bbox="555 174 1417 235">1. Enquiries regarding this Notice should be referred to the AD Focal Point - Certification Directorate, EASA. E-mail: ADs@easa.europa.eu<li data-bbox="555 280 1417 403">2. For any questions concerning the content of this cancellation notice, please contact Hartzell Propeller Inc. Technical Publications Department, One Propeller Place, Piqua, OH 45356; telephone (937) 778-4200; fax (937) 778-4391; E-Mail: techsupport@hartzellprop.com |
|----------|---|