

EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No.: 2008 – 0023</p> <p>Date: 06 February 2008</p>
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.	
Type Approval Holder's Name : AIRBUS	Type/Model designation(s) A330 Aircraft
TCDS Number : EASA A.004	
Foreign AD : Not applicable	
Supersedure : EASA AD 2006-0307	
ATA 05	Time limits / Maintenance checks - Damage-Tolerant Airworthiness Limitation Items (DT ALI)
Manufacturer:	AIRBUS (formerly AIRBUS INDUSTRIE)
Applicability:	AIRBUS A330-300, all certified models, all serial numbers.
Reason:	<p>The limitations for Damage-Tolerant Airworthiness Limitation Items (DT ALI) are currently listed in AIRBUS A330 ALI document reference AI/SE-M4/95A.0089/97, which is referenced in AIRBUS A330 Airworthiness Limitations Section (ALS) Part 2.</p> <p>This Airworthiness Directive (AD) mandates compliance with the requirements defined in AIRBUS A330 ALI document reference AI/SE-M4/95A.0089/97 issue 15 which introduces more restrictive limitations.</p> <p>This AD supersedes EASA AD 2006-0307, which mandated AIRBUS A330 ALI issue 14 referenced AI/SE-M4/95A.0089/97 approved under EASA.A.C.01277 on 17 January 2006.</p>
Effective Date:	20 February 2008
Compliance:	<p>From the effective date of this AD, the following measures are required as indicated:</p> <p>Each Operator must:</p> <ul style="list-style-type: none"> – Review and assess the content of AIRBUS A330 ALI document reference AI/SE-M4/95A.0089/97 issue 15, <p>and</p>

	<ul style="list-style-type: none"> – Incorporate all applicable changes to requirements included in AIRBUS A330 ALI document reference AI/SE-M4/95A.0089/97 issue 15, into the approved maintenance programme, <p>and</p> <ul style="list-style-type: none"> – Comply with any action required by AIRBUS A330 ALI document reference AI/SE-M4/95A.0089/97 issue 15, for example new or reduced thresholds / interval, or more stringent inspections.
Ref. Publications:	<p>AIRBUS A330 ALI Issue 15 referenced AI/SE-M4/95A.0089/97 approved under EASA.A.C.07222 on 09 July 2007</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p>
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can accept Alternative Methods of Compliance for this AD. 2. This AD was posted on 12 December 2007 as PAD 07/022 for consultation until 28 December 2007. The Comment Response Document can be found at http://ad.easa.europa.eu/. 3. Enquiries regarding this Airworthiness Directive should be referred to the AD Focal Point - Certification Directorate, EASA (E-mail: ADs@easa.europa.eu). 4. For any question concerning the technical content of the requirements in this AD, please contact: [AIRBUS SAS - Airworthiness Office - EASA] Fax: + 33 5 61 93 45 80 or + 33 5 61 93 44 51; E-mail: airworthiness@330A330@airbus.com .]

SUPERSEDED