EASA

AIRWORTHINESS DIRECTIVE

AD No.: 2010-0048

Date: 19 March 2010

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

Type Approval Holder's Name:		Type/Model designation(s):	
AIRBUS		A330 aeroplanes	
TCDS Number:	EASA.A.004		
Foreign AD: Not applicable			
Supersedure: This AD supersedes EASA AD 2008-0138 dated 23 July 2008			
ATA 05	Time Limits and Maintenance Checks – Certification Maintenance Requirements – ALS Part 3 – Amendment		
Manufacturer(s):	Airbus (formerly Airbus	s Industrie)	
Applicability:	Airbus A330 aeroplanes, models -201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342 and -343, all manufacturer serial numbers.		
Reason:	The airworthiness limitations are currently distributed in the Airbus A330 Airworthiness Limitations Section (ALS).		
9	Requirements (CMR)	tations applicable to the Certification Maintenance are given in Airbus A330 ALS Part 3, which is bean Aviation Safety Agency (EASA).	
	maintenance requirem	ous A330 ALS Part 3 introduces more restrictive nents and/or airworthiness limitations. Failure to on constitutes an unsafe condition.	
	superseded, and requirestrictive maintenance	ne requirements of EASA AD 2008-0138, which is ires the implementation of the new or more e requirements and/or airworthiness limitations as 30 ALS Part 3 revision 02.	
Effective Date:	02 April 2010		

EASA Form 110 Page 1/2

5		
Required action(s)	Required as indicated:	
and Compliance Time(s):	(1) Within the compliance times defined in the Record of Revisions (ROR) pages of the Airbus A330 ALS Part 3 revision 02:	
	Comply with all applicable maintenance requirements and associated airworthiness limitations included in Airbus A330 ALS Part 3 revision 02.	
	(2) Compliance with the requirements of paragraph (1) of this AD can be demonstrated by:	
	(2.1) Revising as follows, unless accomplished previously, the approved Aeroplane Maintenance Programme from which the Operator or the Owner ensures the continuing airworthiness of each operated aeroplane:	
	Incorporate all maintenance requirements and associated airworthiness limitations specified in Airbus A330 ALS Part 3 revision 02 and that are relevant to the aeroplane model,	
	and	
	(2.2) Complying with the approved Aeroplane Maintenance Programme described in paragraph (2.1) of this AD.	
Ref. Publications:	Airbus A330 ALS Part 3 revision 02, approved by EASA on 16 December 2009. The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.	
Remarks:	If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.	
	 This AD was posted on 14 January 2010 as PAD 10-012 for consultation until 11 February 2010. No comments were received during the consultation period. 	
	3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu .	
	 For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EAZA; E- mail: als@airbus.com 	
5)		

EASA Form 110 Page 2/2