EASA AD No.: 2013-0268

EASA	AIRWORTHINESS DIRECTIVE
	AD No.: 2013-0268
K	Date: 07 November 2013  Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

<b>Design Approval Holder's Name:</b> AIRBUS		Type/Model designation(s): A330 aeroplanes
TCDS Number:	EASA.A.004	
Foreign AD:	Not applicable	
Supersedure:		2006-0159 dated 07 June 2006, EASA AD 2008, EASA AD 2008-0160 dated 22 August 2008 d 30 January 2012.
ATA 05	Time Limits and Mainte Maintenance – ALS Par	enance Checks – Ageing Systems et 4 – Amendment
Manufacturer(s):	Airbus (formerly Airbus Indi	ustrie)
Applicability:	A330-243F, A330-301, A33	2, A330-203, A330-223, A330-243, A330-223F, 80-302, A330-303, A330-321, A330-322, A330-323, A330-343 aeroplanes, all manufacturer serial
Reason:	The airworthiness limitation Airworthiness Limitations S	es for Airbus aeroplanes are currently published in ection (ALS) documents.
		is applicable to the Ageing Systems Maintenance A330 ALS Part 4, which is approved by EASA.
		ALS Part 4 introduces more restrictive maintenance thiness limitations. Failure to comply with these an unsafe condition.
		bove, this AD retains the requirements of EASA AD seded, and requires accomplishment of the actions LS Part 4 at Revision 04.
	2008-0026 and EASA AD 2	persedes EASA AD 2006-0159, EASA AD 2008-0160, whose requirements applicable to A330 sferred into Airbus A330 ALS Part 4.
Effective Date:	21 November 2013	

EASA AD No.: 2013-0268

Required Action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously:			
	(1) From the effective date of this AD, within the compliance times defined in the Record of Revisions (ROR) pages of Airbus A330 ALS Part 4 Revision 04, accomplish the following actions, depending on aeroplane configuration, as specified in Airbus A330 ALS Part 4 Revision 04:			
	(1.1) Replace each component before or upon reaching the applicable life limit, and			
	(1.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks.			
	(2) If, during accomplishment of any task as required by paragraph (1) of this AD, discrepancies are detected, within the applicable compliance time specified in the Airbus maintenance documentation, accomplish the applicable corrective actions in accordance with the instructions specified (or incorporated by reference) in the applicable Airbus maintenance documentation.			
	If no compliance time is identified in the Airbus maintenance documentation, before next flight, accomplish the corrective actions, or contact Airbus for approved instructions and, within the compliance time specified therein, accomplish those instructions accordingly.			
	If any of the discrepancies detected during accomplishment of any task as required by paragraph (1) of this AD is not defined in the Airbus maintenance documentation, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.			
	(3) Compliance with the requirements of paragraphs (1) and (2) of this AD can be demonstrated by:			
	(3.1) Revising as follows the approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane:			
	Incorporate all maintenance requirements and associated airworthiness limitations, as specified in Airbus A330 ALS Part 4 Revision 04, as applicable to aeroplane type, and incorporate the compliance information as specified in paragraph (2) of this AD, and			
Ref. Publications:	Airbus A330 ALS Part 4 Revision 04, approved by EASA on 27 August 2013.			
	The use of later approved variations or revisions of this document is acceptable for compliance with the requirements of this AD.			
Remarks:	If requested and appropriately substantiated, EASA can approve     Alternative Methods of Compliance for this AD.			
	<ol> <li>This AD was posted on 03 October 2013 as PAD 13-152 for consultation until 24 October 2013. No comments were received during the consultation period.</li> </ol>			
	3. Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: <a href="mailto:ADs@easa.europa.eu">ADs@easa.europa.eu</a> .			
	<ol> <li>For any question concerning the technical content of the requirements in this AD, please contact: Airbus – Airworthiness Office – EIAL; E-mail: <u>airworthiness.A330-A340@airbus.com</u>.</li> </ol>			