



<i>AD Number</i>	<i>Status</i>	<i>Approval's Date</i>	<i>TC-Holder</i>	<i>Type/Model</i>	<i>Subject</i>
2007-0053	Supersedure	23/02/2007	Airbus	A310 series	Structure Fatigue – Inspection/Modification
2007-0052	Initial Issue	23/02/2007	Rolls Royce plc	RB211 Trent 500, 700 and 800 series Engines	Engine - IP Compressor Shaft - Visual Borescope Inspection of Balance Land
2007-0047	Initial Issue	23/02/2007	Diamond Aircraft Industries GmbH	DA42	Fuel System – Auxiliary Fuel Tank Venting – Inspection, Modification
2007-0040	Initial Issue	23/02/2007	DG Flugzeugbau GmbH	DG-1000, variant powered sailplanes DG-1000T	Engine Indicating – DEI-NT and Control Unit – Software Update & Flight- & Maintenance Manual Pages – Replacement
2007-0046	Initial Issue	22/02/2007	Rolls Royce plc	RB211 Trent 500 Series Engines	Engine – IP Compressor Drum - Replacement
2007-0034	Initial Issue	22/02/2007	EADS Socata	TB 9 / TB 10 / TB 200	Time Limits - Airworthiness Limitations – New Life Limit for Engine and Nose Landing Gear Mounts
2007-0045	Initial Issue	21/02/2007	Turbomeca	Turboshaft engines – ARRIEL 1A, 1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K, 1K1, 1S, 1S1	Return to Service for Civil Use from an Operator Not Controlled by a Civil Authority
2007-0044	Supersedure	21/02/2007	Turbomeca	Turboshaft engines – ARRIEL 2B, 2B1, 2B1A	Engine Fuel and Control - Hydromechanical Metering Unit (HMU) - Visual Inspection of the Drive-Link Splines
2007-0043	Initial Issue	21/02/2007	Agusta S.p.A	AB206A and AB206B	Exhaust – Exhaust Duct Grooved Clamps – Inspection/Replacement
2007-0042	Initial Issue	21/02/2007	Alexander Schleicher GmbH & Co.	ASW 28-18 E	Powerplant – RPM Sensor, Fuel Pump & Instrument Hardware Improvements – Installation
2007-0041	Initial Issue	21/02/2007	Agusta S.p.A	A109A, A109AII, A109C	Exhaust – Exhaust Duct Grooved Clamps – Inspection/Replacement
2007-0038	Initial Issue	21/02/2007	Agusta S.p.A	A 109 E	Hydraulic Power - Hydraulic Pipes P/N's 109-0761-64-103 and 109-0761-65-103 – Inspection / Replacement
2007-0039-E	Initial Issue	16/02/2007	Short Brothers PLC	SD3 series aeroplanes	Engine Controls / Landing Gear – Control Cables – Inspection/Replacement
2007-0037	Supersedure	15/02/2007	Airbus	A300-600 and A300-600ST BELUGA aircraft	Landing Gear – Tachometer Mechanical Connection and Proximity Sensor Electrical Loom – Modification
2007-0036-E	Initial Issue	14/02/2007	Airbus	A318, A319, A320 and A321 aircraft	Power Plant – Forward Engine Mount Bolts – Inspection / Replacement / Retorque
2007-0035-E	Initial Issue	14/02/2007	Turbomeca	TM 333 2B2 Turboshaft engines	Engine Air System – Casing/Rear Bearing P2 Air Pipe – Inspection/Replacement
2007-0033	Supersedure	13/02/2007	Société de Motorisations Aéronautiques (SMA)	SR305-230	Engine Controls - Electronic Control Unit (ECU) - Replacement
2006-0284R1	Revision	13/02/2007	Airbus	A310 and A300-600 aircraft	Electrical Power - Prevention against Fuel Tank Explosion Risks - Fuel Pump Wiring - Modification
2007-0032	Initial Issue	12/02/2007	Dassault Aviation	Falcon 2000EX (version F2000EX EASy) and Falcon 900EX (versions F900EX EASy and F900DX)	Indicating/Recording Systems - Incomplete Software Integrity Checks & Untimely Inhibition of Flap Asymmetry Detection - Verification / Modification