



<i>AD Number</i>	<i>Status</i>	<i>Approval's Date</i>	<i>TC-Holder</i>	<i>Type/Model</i>	<i>Subject</i>
2007-0063	Initial Issue	08/03/2007	Turbomeca	ARRIEL 2S1 and ARRIEL 2S2 turboshaft engines	Engine Fuel & Control – Hydro Mechanical Unit (HMU) Fuel Filter Drain Screw – Replacement
2006-0236R1	Revision	08/03/2007	Airbus	A319 and A320 aircraft	Fuel, Wings - Fuel system – Labels in Fuel Tank
2007-0062	Initial Issue	07/03/2007	Airbus	A300, A300-600 and A300-600ST aircraft	Wings – Trailing Edge Flap Deflectors – Inspection/Repair
2007-0061-E	Supersedure	07/03/2007	Turbomeca	TURMO turboshaft engines	Engine - Flexible lubrication pipe between tank and cooler and flexible lubrication pipe between intermediate bearing and oil pump - Inspection
2007-0060-E	Initial Issue	07/03/2007	BRP-Rotax GmbH & Co. KG	Rotax 912 A series Rotax 912 F series Rotax 912 S series	Engine Fuel and Control - Fuel Pump - Replacement
2007-0059	Initial Issue	05/03/2007	Aerotechnic Vertriebs- u. Service GmbH	Installation of Honeywell CAS67A ACAS System	Navigation – Honeywell ACAS II System – Modification [Installation of Decoupling Diodes in HDG and ATT Valid Lines]
2007-0058	Supersedure	01/03/2007	BAE Systems (Operations) Limited	BAe 146 and Avro 146-RJ	Stabilisers – Elevator Drain Holes – Modification
2007-0057	Initial Issue	01/03/2007	Turbomeca	Turbo-shaft engine ARRIUS 2F	Engine - Gas Generator Front Bearing- Modification
2007-0056	Supersedure	01/03/2007	BAE Systems (Operations) Limited	Jetstream 4100	Wings – Wing Upper Splice Plate – Inspection
2007-0036R1	Revision	27/02/2007	Airbus	A318, A319, A320 and A321 aircraft	Power Plant – Forward Engine Mount Bolts – Inspection / Replacement / Retorque
NL-2007-001	Initial Issue	26/02/2007	Fokker Services B.V.	Fokker F28 Mark 0070 and Fokker F28 Mark 0100	MAIN LANDING GEAR – MESSIER-DOWTY MAIN LANDING GEAR – REPLACEMENT UPPER TORQUE LINK PIN
NL-2005-005-R1	Revision	26/02/2007	Fokker Services B.V.	Fokker F28 Mark 0100	EQUIPMENT/FURNISCHING - PASSENGER SERVICE UNIT, SPEAKER, OXYGEN & BLIND PANELS ATTACHEMENTS - MODIFICATION
NL-2002-062 R1	Revision	26/02/2007	Fokker Services B.V.	Fokker F28 Mark 0070 and Fokker F28 Mark 0100	TIME LIMITS/MAINTENANCE CHECKS - MAINTENANCE REQUIREMENTS - INTRODUCTION
NL-2002-061 R1	Revision	26/02/2007	Fokker Services B.V.	Model F27 Mark 050, Mark 0502 and Mark 0604	TIME LIMITS/MAINTENANCE CHECKS - MAINTENANCE REQUIREMENTS - INTRODUCTION
2007-0055	Initial Issue	26/02/2007	EADS Socata	TBM 700	Wing – Flap carriage roller pins - Inspection
2007-0050-E	Initial Issue	26/02/2007	Rolls-Royce Deutschland Ltd. & Co. KG.	BR700-715 series, all models	Engine - High Pressure Compressor - Front Drum Assembly