



<i>AD Number</i>	<i>Status</i>	<i>Approval's Date</i>	<i>TC-Holder</i>	<i>Type/Model</i>	<i>Subject</i>
2007-0077-E	Initial Issue	23/03/2007	Lange Flugzeugbau GmbH	E1 Antares	Flight Controls - Rudder cables - Inspection / Replacement
2006-0286R1	Revision	22/03/2007	Intertechnique	Oxygen Reserve Cylinders having Part Number (P/N) GLF(XXX)-(X), GLD(XXX)-(X), PC2300 and SLF300	Oxygen - Oxygen Reserve Cylinders – Removal/Emptying
2007-0076	Initial Issue	21/03/2007	BAE Systems (Operations) Limited	BAe 146 and AVRO 146-RJ	Hydraulic Power – Accumulators – Inspection/Replacement
2007-0075	Initial Issue	20/03/2007	BAE Systems (Operations) Limited	BAe 146 and AVRO 146-RJ	Fuselage - Aft Fuselage Skin under APU Heat Shield - Inspection / Repair
2007-0074	Supersedure	20/03/2007	BAE Systems (Operations) Limited	Jetstream Series 3200	Time Limits - Airworthiness Limitations
2007-0073	Initial Issue	19/03/2007	Dassault Aviation	FALCON 900EX and FALCON 2000EX (EASy version)	Oxygen - Incompatible passengers mask boxes - Replacement
2007-0072-E	Initial Issue	16/03/2007	PZL Swidnik S.A.	W-3A, W-3AS	Hydraulic System - Pressure Lines - Modification
2007-0071	Initial Issue	16/03/2007	Apex Aircraft	DR 400 series	Wings - Main spar and fabric covering - Reinforcement / Modification / Inspection
2007-0070	Supersedure	16/03/2007	Airbus	A330 series	Landing gear - Nose Wheel Steering System - Rotating Sleeve - Inspection / Modification
2007-0069	Supersedure	16/03/2007	Airbus	A340-200/-300 series	Landing gear - Nose Wheel Steering System - Rotating Sleeve - Inspection / Modification
2007-0068	Initial Issue	14/03/2007	Airbus	A300-600 aircraft	Landing Gear – Parking Brake Pressure Switch Wiring – Modification
2007-0065	Initial Issue	14/03/2007	Airbus	A318, A319, A320 and A321 series	Landing gear – Normal extension and retraction – Inspection of the selector valves 40GA and 41GA
2007-0067	Initial Issue	13/03/2007	Airbus	A319, A320	Wing - Center and Outer Wing Box at level of Rib 1 Junction - Inspection
2007-0066	Supersedure	13/03/2007	Airbus	A300 aircraft	Electrical Power - Prevention against Fuel Tank Explosion Risks - Fuel Pump Wiring - Modification
2007-0064	Initial Issue	13/03/2007	Airbus	A319, A320 and A321 aircraft	Wing - Dry Bay Skin - Inspection