



<i>AD Number</i>	<i>Status</i>	<i>Approval's Date</i>	<i>TC-Holder</i>	<i>Type/Model</i>	<i>Subject</i>
2007-0125	Initial Issue	04/05/2007	Airbus	A330, A340-200/-300 aircraft	Fuselage – Longitudinal joint at Stringer 28 RH between FR18 and FR19- Inspection
2007-0124	Supersedure	04/05/2007	Airbus	A340-500/-600 series	Flight Controls – Elevator Servo Controls - Dispatch Restriction / Inspection
2007-0123	Supersedure	04/05/2007	EMBRAER - Empresa Brasileira de Aeronautica S.A.	EMB-110 Series aircraft	Navigation - Attitude indicator – Modification/Addition
2007-0116-E	Initial Issue	04/05/2007	Rolls-Royce Deutschland Ltd. & Co. KG.	BR700-715A1-30, BR700-715B1-30, BR700-715C1-30	Engine - Low Pressure (LP) Compressor (Fan) Disc Assembly – Reduction of the Time Limits Manual maximum approved lives
2007-0122	Initial Issue	03/05/2007	Fokker Services B.V.	F28 Mark 0070 and Mark 0100	Fuel System - Crossfeed Valve Actuators and Fuel Fire Shut off Valve Actuators - Temporary Maintenance Tasks
2007-0121	Initial Issue	03/05/2007	Eurocopter Deutschland GmbH	MBB-BK 117 C2 helicopters	Fire Protection System – Fire Extinguishing System Injection Tube Clamps – Replacement
2007-0120	Initial Issue	03/05/2007	Bombardier Inc.	CL-600-2B16 (604 variant)	Navigation – Mode S Transponder Wiring – Modification
2007-0119	Initial Issue	02/05/2007	Dassault Aviation	FALCON 2000EX (version F2000EX EASy)	Fire Protection - Engine fire detection system - Modification
2007-0118	Initial Issue	02/05/2007	Dassault Aviation	Fan Jet Falcon all series, MYSTERE-FALCON 20-()5,MYSTERE-FALCON 20-GF	Fuselage Structure - Cockpit windows frames - Modification
2007-0117	Initial Issue	02/05/2007	Turbomeca	ARRIEL 2B, 2C and 2S series turboshaft engines	Return to Service for Civil Use from an Operator Not Controlled by a Civil Authority
2007-0114	Initial Issue	02/05/2007	Pilatus Aircraft Ltd.	PC-6	Wing - Upper wing strut fitting - Inspection/Replacement
2007-0096R1	Revision	02/05/2007	Airbus	A310	Fuel Tank Safety - ALS Part 5 - Fuel Airworthiness Limitations (FAL)
2007-0095R1	Revision	02/05/2007	Airbus	A300-600, A300-600ST	Fuel Tank Safety ALS Part 5 - Fuel Airworthiness Limitations (FAL)
2007-0094R1	Revision	02/05/2007	Airbus	A300	Fuel Tank Safety ALS Part 5 - Fuel Airworthiness Limitations (FAL)
2007-0115	Supersedure	27/04/2007	Eurocopter	EC 225 LP Helicopters	Ice and Rain Protection - Main Rotor Blade De-Icing System Harness Connectors – Check / Replacement
2007-0112	Initial Issue	27/04/2007	ATR - Avions de Transport Régional	ATR 42-200, 42-300 and 42-320	Main landing gear – Side brace assembly - Upper arm – Inspection / Replacement
2007-0113	Supersedure	26/04/2007	Rolls-Royce Deutschland Ltd. & Co. KG.	Tay 650-15, Tay 650-15/10, Tay 651-54	Engine – Undetected Root Cracks in LP Compressor Rotor Blades
2007-0111	Initial Issue	25/04/2007	Airbus	A310	Fuselage - Frame 55/58 Butt Joint - Reinforcement
2007-0110-E	Initial Issue	23/04/2007	MORAVAN AVIATION s.r.o	Z 42 series	Airworthiness Limitations- Permissible Aerobatic manoeuvres in Utility category - Modification