



<i>AD Number</i>	<i>Status</i>	<i>Approval's Date</i>	<i>TC-Holder</i>	<i>Type/Model</i>	<i>Subject</i>
2007-0144	Initial Issue	18/05/2007	Turbomeca	MAKILA 1 turbo-shaft engines	Engine Control Unit (ECU) - Hardware - Modification
2007-0143	Supersedure	18/05/2007	Turbomeca	MAKILA 1 turbo-shaft engines	Digital Engine Control Unit (DECU) – Software - Modification
2007-0142	Initial Issue	18/05/2007	Agusta S.p.A	AB139 and AW139 helicopters	Windows – Cockpit Doors, Windows and Sealing – Inspection / Repair / Replacement
2007-0140	Supersedure	16/05/2007	Airbus	A340-500/ -600	Electrical Installation – Electrical Wiring Route 3G/3E & Hydraulic Pipe at Frame 53.8 – Modification
2007-0137	Initial Issue	16/05/2007	Dassault Aviation	FALCON 2000EX	Ice and rain protection - Wing anti-ice monitoring system - Modification
2007-0139-E	Initial Issue	15/05/2007	Eurocopter	AS 350 and AS 355	Fuselage - Center cross-member under the cabin floor - Inspection / Modification
2007-0138-E	Supersedure	15/05/2007	Eurocopter	AS 350 and AS 355	Tail Rotor - Tail rotor blades skin - Inspection / Repair
2007-0136	Initial Issue	14/05/2007	Rolls Royce plc	RB211 700 series engines	Engine – IP Compressor Shaft - Inspection
2007-0135-E	Initial Issue	14/05/2007	Grob Aerospace GmbH	ASTIR CS, Model G102 “ASTIR III” series	Flight Controls – Flight Control System Welded Components – Inspection / Replacement
2007-0134	Initial Issue	14/05/2007	Eurocopter	AS 332 and EC 225 helicopters	Main Rotor Drive – Engine-to-Main Gearbox (MGB) Coupling Shaft Flange Threaded Attachment Bolt Assembly – Replacement
2007-0133	Supersedure	11/05/2007	Airbus	A330 & A340 aircraft	Time Limits - Safe Life Airworthiness Limitation Items – ALS Part 1
2007-0132	Supersedure	11/05/2007	Slingsby Advanced Composites, Ltd.	T67 series	Flight Controls – Rudder Pedals and Floor – Inspection
2007-0131-E	Initial Issue	11/05/2007	Eurocopter	AS 355	Rotor Flight Controls - Load Compensator Levers - Inspection / Replacement.
2007-0130-CN	Initial Issue	10/05/2007	Rolls-Royce Deutschland Ltd. & Co. KG.	LBA LTA-Nr.: 2000-358/2 (BR700-715A1-30, BR700-715B1-30, BR700-715C1-30)	Engine - High pressure turbine stage 1 and stage 2 disk - Reduction of the Time Limits Manual maximum approved lives for specific disks
2007-0129	Supersedure	10/05/2007	Eurocopter	SA 365 N and AS 365 N helicopters	Main Rotor Drive – Main Gearbox (MGB) Suspension Diagonal Cross-Member – Check/Replacement
2006-0344R1	Revision	10/05/2007	Eurocopter	EC 130 B4 helicopters	Equipment & Furnishings – Emergency Flotation Gear – Electrical harnesses and Attachment – Check/Repair/Replacement/Installation
2007-0128-E	Initial Issue	07/05/2007	S.E.I. Servizi Elicotteristici Italiani SpA	NH-500D helicopters	Tail Rotor – Blade Part Number (P/N) 369D21613 – Identification / Inspection / Replacement
2007-0127	Initial Issue	07/05/2007	Société de Motorisations Aéronautiques (SMA)	SR305-230	Engine Primary Exhaust Assembly – Inspection and Replacement
2007-0126	Supersedure	07/05/2007	Turbomeca	ARRIEL 2B turboshaft engines	Engine Fuel & Control – Hydro Mechanical Unit (HMU) Constant Delta Pressure Valve Diaphragm – Replacement
2007-0122	Correction	07/05/2007	Fokker Services B.V.	F28 Mark 0070 and Mark 0100	Fuel System - Crossfeed Valve Actuators and Fuel Fire Shut off Valve Actuators - Temporary Maintenance Tasks