

Bi-Weekly Report of EASA published ADs between 30/07/2007 - 12/08/2007

easa.europa.eu

		Released			
AD Number	Status	on	TC-Holder	Type/Model	Subject
2007-0218	Supersedure	10/08/2007	Airbus	A318, A319, A320 and A321 aircraft	Fuel – Main Fuel Pump System / Fuel Pumps – Airworthiness Limitations / Inspection / Replacement
2007-0217	Supersedure	09/08/2007	Airbus	AIRBUS A318, A319, A320 and A321 aircraft	Navigation – NORTHROP-GRUMMAN (previously LITTON) ADIRU / Replacement
2007-0216-E	Initial Issue	08/08/2007	Airbus	A330 aircraft	Fuel – Engine Feed Line – Operational procedure
2007-0215	Supersedure	08/08/2007	Airbus	A330 Aircraft	Engine – Icing Conditions during Descent – Operational Procedure and Dispatch Restriction / Modification
2007-0208-CN	Initial Issue	08/08/2007	Dowty Propeller Aerospace	Propeller R408/6-123-F/17	Propeller – High Crosswind Operation Life Limitation
2007-0204	Initial Issue	08/08/2007	Saab Aircraft AB	SAAB 2000	Powerplant Aft Engine Mounting Centre Bracket – Inspection/Rework
2007-0214	Supersedure	07/08/2007	Airbus	A318, A319, A320 and A321	Equipment/Furnishings - 103VU Box - Hinge Pin Stopper - Modification
2007-0213	Supersedure	07/08/2007	Airbus	A318, A319, A320 and A321 series	Wings – Outer Wing Main Landing Gear Support Rib 5 Fitting – Inspection / Modification
2007-0212	Initial Issue	07/08/2007	Aircraft Industries a.s.	L13 "BLANÍK" sailplanes	Flight Controls – Control Sticks and Bridge – Inspection/Replacement
2007-0211	Supersedure	07/08/2007	Eurocopter	EC 120B	Tail Rotor Drive - Rear Drive Shaft Friction Ring - Inspection/Replacement
2007-0210	Initial Issue	06/08/2007	Apex Aircraft	All models (see Applicability)	Fuel – Fuel Pump Electrical Grounding – Modification
2007-0209-E	Supersedure	06/08/2007	Eurocopter	AS 355 helicopters	Rotor Drive – Main Gearbox (MGB) Lubrication Pump – Inspection / Replacement
2007-0206	Supersedure	06/08/2007	Rolls Royce plc	RB211 TRENT 768-60, 772-60, 772B-60	Engine – HP Compressor – Test/Modification
2007-0207	Initial Issue	03/08/2007	Airbus	A340-500/-600 series	Wings – Centre Wing Box / Rear Spar Vertical Cruciform at Frame 47 – Inspection / Repair
2007-0205	Initial Issue	03/08/2007	Turbomeca	Turbo-shaft engine ASTAZOU XIV	Change to Civil Use Following Use by an Operator Not Controlled by a Civil Authority
2006-0340R1	Correction	02/08/2007	Eurocopter	EC 225 LP and AS 332 C, C1, L, L1 and L2 helicopters	Equipment and Furnishings - Seal of the Jettisonable Window Panel - Inspection / Rework
2007-0203	Supersedure	01/08/2007	Fokker Services B.V.	F27 Mark 050, Mark 0502 and Mark 0604 aircraft	Propellers – Feathering Pump Interface Bobbin – Inspection / Replacement
2007-0202	Initial Issue	01/08/2007	Rolls Royce plc	RB211 Trent 768-60, 772-60, 772B-60 and 772C-60	Engine – HP/IP Turbine Bearing Oil Vent Tube Restrictor – Inspection / Cleaning / Replacement
2007-0201	Supersedure	01/08/2007	Rolls Royce plc	RB211 Trent 768-60, 772-60, 772B-60 and 772C-60	Engine – HP/IP Turbine Bearing Oil Vent Tubes – Inspection / Cleaning / Replacement
2007-0179	Initial Issue	31/07/2007	ATR - Avions de Transport Régional	ATR 42 and ATR72 series	Ice & Rain Protection - Pitot Probe Resistance & Low Current Sensor - Inspection / Replacement
2007-0200-E	Supersedure	30/07/2007	MORAVAN AVIATION s.r.o	Z 42, Z 142 and Z 242 series	Introduction of new Airworthiness- and Operating Limitations



Bi-Weekly Report of EASA published ADs between 30/07/2007 - 12/08/2007



AD Number	Status	Released on	TC-Holder	Type/Model	Subject
2007-0194-E	Initial Issue	30/07/2007	Grob Aerospace GmbH	TWIN ASTIR and G103 Gliders, all variants; and G103C TWIN III SL Powered Sailplanes	Fuselage, Wing & Stabilisers Structure – Inspection/Repair

Biweekly_16-2007 Issued: 15/08/2007 Page 2 of 2