

| AD number   | Issue Date | TC Holder                    | Type              | Subject   |
|-------------|------------|------------------------------|-------------------|---|
| 2008-0095   | 2008-05-16 | DG-FLUGZEUGBAU               | DG-500MB          | Powerplant - Extension Retraction Mechanism - Modification  |
| 2008-0094   | 2008-05-16 | BAE SYSTEMS (OPERATIONS) LTD | JETSTREAM4100     | Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation   |
| 2008-0092R1 | 2008-05-15 | BAE SYSTEMS (OPERATIONS) LTD | AVRO146RJ, BAE146 | Fuselage - Frames 15, 18, 41 and 43 Web/Flange and Door Hinge Bosses - Inspection / Repair / Rework                   |
| 2008-0088   | 2008-05-13 | FOKKER SERVICES              | F28               | Engine Controls - Reverse Thrust Control Normal Maximum (Second) Detent - Replacement                                 |
| 2008-0090   | 2008-05-13 | FOKKER SERVICES              | F28               | Indicating / Recording Systems - Flight Warning Computer - Replacement  |
| 2008-0089   | 2008-05-13 | FOKKER SERVICES              | F28               | Engine Controls - Reverse Thrust Control Normal Maximum (Second) Detent - Removal                                     |
| 2008-0086   | 2008-05-13 | DIAMOND                      | DA42, DA42M       | Flight Controls - Aileron Bellcrank and Rod Ends - Replacement  |
| 2008-0091   | 2008-05-13 | FOKKER SERVICES              | F27, F28          | Electrical Power - AC Bus Transfer Terminal Contactor - Modification  |
| 2008-0087-E | 2008-05-08 | 328 Support Services GmbH    | 328-100, 328-300  | Wings - Lower Inner Panel - Inspection / Repair   |
| 2008-0077   | 2008-05-06 | TURBOMECA                    | ARRIEL 2          | [Corrected] Engine Fuel & Control - Hydro Mechanical Unit (HMU) - Low Fuel Pressure Switch - Inspection / Replacement |
| 2008-0085-E | 2008-05-06 | DASSAULT                     | FALCON 7X         | Electrical System - Secondary Power Distribution Box - Replacement  |
| 2008-0083   | 2008-05-05 | PILATUS                      | PC6               | Fuselage - Self-locking Stop Nuts - Replacement   |

Biweekly 10-2008 Issued on 19/05/2008