



Publ. number	Issue Date	TC Holder	Type	Subject
2008-0219-E	2008-12-11	EUROCOPTER	AS 332, EC225	Fuselage - Intermediate Gear Box (IGB) Fairing Gutter - Check / Replacement
2008-0218	2008-12-10	ATR	ATR42, ATR72	Electrical / Electronic - Wire Bundles in the Rear Baggage Zone - Protection and Clamping
2008-0217	2008-12-10	RUAG Aerospace Services, GmbH	228	Flight Controls - Aileron Trim Actuator and Rod Spring Lever Attachment Bracket Riveting - Inspection / Modification.
2008-0216	2008-12-09	AIRBUS	A380	Wings - Movable Flap Track Fairing - Inspection / Replacement
CF-2008-34	2008-12-09	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	APU Start Contactor Assembly Fuse Blocks Inspection / Replacement
CF-2008-08R1	2008-12-08	PRATT & WHITNEY CANADA	PW305	Engine Fan Blade Fracture
2008-0214-E	2008-12-08	EUROCOPTER	AS 350	Equipment & Furnishing - Emergency Flotation Gear - Inspection / Limitation / Replacement
2008-24-07	2008-12-08	ECLIPSE AVIATION Corp.	ECLIPSE	Airplane Flight Manual (AFM) and Maximum Operating Altitude Limitation - Introduction
2008-0213	2008-12-08	AIRBUS	A330	Fuselage - Centre Fuselage - FR 40 Keel beam flange - Inspection/Repair
2006-20-51R1	2008-12-05	BOEING	777	Engine thrust rollback during takeoff
2008-0215	2008-12-05	THIELERT AIRCRAFT ENGINES	TAE125	Replacement of Rail Pressure Control Valve - Modification of VRail Plug - Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
2008-18-06	2008-12-04	MCDONNELL DOUGLAS	DC9	Tail Cone Evacuation Slide per Supplemental Type Certificate ST735SO - Modification / Test
CF-2008-32R2	2008-12-04	BOMBARDIER	CL600 2A12, CL600 2B16	Engine Throttle Control Gearbox Wear Inspection
2008-0211	2008-12-04	AIRBUS	A310	Wings - Wing Top Skin Panels 1 and 2 Rib 2 - Inspection / Repair
2008-0212	2008-12-04	AIRBUS	A310	Fuselage - Upper Frame Bases-to-Arches Junctions from FR43 to FR46 - Modification
2008-0204-E	2008-12-04	EUROCOPTER	AS 365, SA 365	Stabilizers - Never-Exceed Speed (VNE) and Rate-of-Descent (R/D) - Limitations
2008-0210	2008-12-03	AIRBUS	A340	Exhaust - Separation of Inner Fixed Structure (IFS) Panels - Temperature Monitoring / Modification
2008-20-05	2008-12-02	MD HELICOPTER	600	Correction - Tailboom attachment fittings and upper longerons - Modification / Inspections
2008-0205-E	2008-12-02	EUROCOPTER	AS 350	Rotors Flight Control - Collective Pitch Lever Locking Stud - Inspection / Repair
2008-24-08	2008-12-02	BOEING	737	Escape slides