



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0074	2010-04-16	AIRBUS	A300-600	Fuel System - Fuel Tank Electrical Bonding - Inspection / Modification [Fuel Tank Safety]
2010-0071	2010-04-15	AIRBUS	A318, A319, A320, A321	Time Limits and Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment
2010-0072	2010-04-15	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Landing Gear - Nose Landing Gear Main Fitting - Inspection / Replacement
2009-0202R1	2010-04-15	AIRBUS	A330, A340	Navigation - Pitot Probe Quick-Disconnect Union - Torque Check
2010-0073	2010-04-15	DASSAULT	FALCON 7X	Electrical Power - Transient Voltage Suppressor Diodes - Inspection/Replacement
2010-0038	2010-04-15	AIRBUS	A380	Flight Controls - Outboard Elevator Electro Hydrostatic Actuator (EHA) - Inspection / Replacement
2010-0060R1	2010-04-14	ROLLS-ROYCE DEUTSCHLAND	Tay	Engine - Low Pressure Turbine Discs Stage 2 and 3 - Inspection/Replacement
2010-0053R1	2010-04-14	GROB	ASTIR CS, ASTIR CS 77, G102 STANDARD ASTIR III, SPEED ASTIR II, SPEED ASTIR IIb, STANDARD ASTIR II, TWIN ASTIR	Waterballast - Hose-Fuselage Connectors of the Water Ballast Dumping System - Inspection / Repair
2010-0070	2010-04-14	AIRBUS	A300-600, A300-600ST BELUGA, A310	Equipment / Furnishings - Pilot and Co-pilot Seats - Deactivation of Powered Movement - Modification
2008-0051R1	2010-04-14	AIRBUS	A320	Fuel / Electrical Power - Prevention of Fuel Tank Explosion Risks - Electrical Cables - Modification
2010-0069	2010-04-14	SAAB AB, SAAB AEROSYSTEMS	2000	Landing Gear - Main Landing Gear (MLG) Shock Strut Actuator Mounting Bracket Attachment Bolts - Inspection
2010-0068-E	2010-04-13	TURBOMECA	MAKILA 2	[Correction] Engine Fuel & Control - Digital Engine Control Unit - Replacement
2010-0067	2010-04-12	ROCKWELL COLLINS	TDR-94 Transponders, TDR-94D Transponders	Navigation - Mode S Transponder - Check / Modification
2007-0276R1	2010-04-12	AIRBUS	A318, A319, A320, A321	[Correction 2] Equipment / Furnishing - 80VU Rack Attachments - Inspection / Repair / Replacement
US-2010-07-03	2010-04-09	BOEING	747	Fuselage - Sections 41 and 42 Upper Deck Floor Panels and Beams - Inspection / Repair
CF-2009-01R1	2010-04-09	BOMBARDIER	DHC-8	Dual AC Generator Shutdown
CF-2010-10	2010-04-08	BOMBARDIER	BD700 1A10, BD700 1A11	Hydraulic Systems Number 2 and 3: Damage caused by Main Landing Gear Tire Failure



Publ. number	Issue Date	TC Holder	Type	Subject
US-2010-07-08	2010-04-08	LYCOMING, TELEDYNE CONTINENTAL	HIO-360, IO-320, IO-360, IO-540, IO-720, LIO-320, LTIO-540, LTO-360, O-360, O-540, TIO-540, TIO-541, TO-360, TVO-435, GTSIO-520, IO-360, IO-470, LTSIO-360, O-470, TSIO-360, TSIO-470, TSIO-520, TSIO-550	Kelly Aerospace Energy Systems, LLC (KAES) Rebuilt Turbochargers - Identification / Replacement
US-2010-06-51	2010-04-07	BOEING	737	Elevator Tab Control Mechanism - Aft Attach Lugs - Inspection