



| Publ. number | Issue Date | TC Holder | Type | Subject |
|-----------------|------------|-------------------------------|------------------------------------|--|
| 2010-0071R1 | 2010-05-28 | AIRBUS | A318, A319, A320, A321 | Time Limits and Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment |
| CF-2003-23R3 | 2010-05-27 | BOMBARDIER | CL600 2C10, CL600 2D15, CL600 2D24 | Main Landing Gear Door Separation During Flight |
| 2010-0098 | 2010-05-27 | BAE SYSTEMS (OPERATIONS) LTD | JETSTREAM4100 | Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment / Implementation |
| 2010-0097 | 2010-05-26 | ROLLS-ROYCE PLC | RB211 TRENT 800 | Engine - Low Pressure Compressor Fan Blades - Inspection |
| CF-2010-14 | 2010-05-26 | BOMBARDIER | BD700 1A10, BD700 1A11 | Doors - Passenger Door - Tensator Springs Failure |
| 2010-0099 | 2010-05-26 | CENTRAIR | 101 | Flight Controls - Rudder Bar Locking Adjustment Tube - Inspection/Replacement |
| 2010-0095 | 2010-05-26 | BAE SYSTEMS (OPERATIONS) LTD | ATP | Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment / Implementation |
| CF-2010-15 | 2010-05-26 | BOMBARDIER | CL600 2C10, CL600 2D15, CL600 2D24 | Main Landing Gear - Piston Axle Failure |
| 2010-0100-E | 2010-05-26 | EUROCOPTER | AS 365, SA 365 | Navigation - Vertical Gyro Unit Data Output - Operational Limitation / Operational procedure / Reinforcement |
| BR-2010-01-02R1 | 2010-05-26 | EMBRAER | ERJ190 | Master Minimum Equipment List (MMEL) Section 21 Item 24-04 - Amendment - Dispatch Limitation |
| 2010-0015-CN | 2010-05-25 | SIKORSKY | S92 | [Corrected] Main Rotor Drive - Main Gearbox (MGB) Filter Bowl Assembly - Replacement |
| GA8-5-Amdt4 | 2010-05-25 | GIPPSLAND | GA8 | Horizontal Stabiliser Inspection |
| 2010-0096 | 2010-05-25 | EUROCOPTER DEUTSCHLAND | BK 117 | Airworthiness Limitations - Tail Rotor Intermediate Gear Box (IGB) Bevel Gear - Reduced Life Limit |
| US-2010-10-03 | 2010-05-21 | SIKORSKY | S92 | Main Rotor Drive - Main Gearbox (MGB) Filter Bowl Assembly - Replacement |
| US-2009-26-09 | 2010-05-21 | GENERAL ELECTRIC | CF34 | [Correction] Engine - Fan Disks - Inspections / Replacement |
| 2010-0092 | 2010-05-21 | AIRBUS | A300-600, A310 | Flight Controls - Trimmable Horizontal Stabilizer Actuator (THSA) Upper Attachment Gimbal - Inspection |
| 2010-0084R1 | 2010-05-20 | FISCHER + ENTWICKLUNGEN GMBH | ASTIR CS 77 TOP, ASTIR CS TOP | Waterballast - Hose-Fuselage Connectors of the Water Ballast Dumping System - Inspection / Repair |
| US-2010-10-20 | 2010-05-20 | MCDONNELL DOUGLAS | DC9 | Fuel - Auxiliary Fuel Tank(s) - Inspection |
| US-2010-10-05 | 2010-05-20 | BOEING | 747 | Fuselage Skin Lap Joints - Inspection / Repair / Modification |
| US-2010-10-10 | 2010-05-20 | HAWKER BEECHCRAFT CORPORATION | 390 | Essential Bus Lightning Strike Protection WIRING - Inspection / Rework |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|-------------------------------|-------------------------------------|---|
| 2010-0094-E | 2010-05-20 | Zaklady Lotnicze Marganski | Swift S-1 | Flight Controls - Control Column - Inspection / Repair |
| 2010-0093 | 2010-05-20 | PILATUS | PC12 | Engine Controls - Power Control Lever Reverse Thrust Latch - Inspection / Modification |
| US-2010-11-52 | 2010-05-20 | SIKORSKY | S76 | LITEF Attitude Heading and Reference System (AHRS) - Placard / Rotorcraft Flight Manual - Limitations |
| US-2010-10-02 | 2010-05-19 | SIKORSKY | S76 | Main Rotor Servo Actuator - Inspection / Replacement / Modification / Re-identification |
| 2010-0091 | 2010-05-19 | AIRBUS | A318, A319, A320, A321 | Stabilizers - Elevators - Inspection |
| US-2010-09-12 | 2010-05-18 | MCDONNELL DOUGLAS | DC10, MD10, MD11 | Fuel - Fuel Tanks Fill Valve Controllers Electrical Bonding Jumpers - Installation |
| 2010-0090 | 2010-05-18 | SOCATA | TBM700 | Oxygen - Chemical Oxygen Generator - Modification |
| 2008-0034R1 | 2010-05-18 | AIRBUS | A320 | Hydraulic Power - Ram Air Turbine (RAT) Gerotor Pump - Replacement |
| 2010-0062R1 | 2010-05-17 | FIRE FIGHTING ENTERPRISES LTD | Halon 1211 (BCF) Fire Extinguishers | Fire Protection - Halon 1211 Fire Extinguishers - Identification / Replacement |