



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0107	2010-06-11	GROB	G103C	Propellers - Propeller Assembly - Inspection / Repair
2010-0111-E	2010-06-11	THIELERT AIRCRAFT ENGINES	TAE125	[Correction] Engine - Clutch Assembly - Identification / Replacement
US-2010-12-10	2010-06-10	GENERAL ELECTRIC	CF6-45, CF6-50	Low Pressure Turbine (LPT) Rotor Discs and High Pressure Turbine (HPT) Rotor Blades Inspection / Replacement - Exhaust Gas Temperature (EGT) System Checks
2010-0110-CN	2010-06-10	DG-FLUGZEUGBAU	LS 1-0	CANCELLATION NOTICE - Luftfahrt-Bundesamt (LBA) Airworthiness Directive 1999-378 dated 16 December 1999 Increase of Service Life
2010-0103	2010-06-09	AIRBUS	A330, A340	Electric and Electronic Common Installation - Cable Loom Installation - Modification
2010-0105	2010-06-08	AIRBUS	A380	Nacelle and Pylons - Aft Pylon Fairing / Fasteners - Inspection
2010-0104	2010-06-08	AIRBUS	A340	Air Conditioning - Pack Bay Ventilation Ducting - Inspection
2010-0102	2010-06-08	AIRBUS	A300	Landing Gear - Main Landing Gear (MLG) Retraction Actuator Sliding Rod - Inspection / Replacement
CF-2010-17	2010-06-08	BELL CANADA	427	Tail Rotor Driveshaft Hanger Bearing Bracket - Cracking Due To Tooling Mark
2010-0108-E	2010-06-08	Zaklad Szybowcowy "Jezow" Henryk Mynarski	PW-6U	Horizontal Stabilizer - Rear Attachment Fitting - Inspection / Repair
US-2010-10-16	2010-06-07	AERONAUTICAL ACCESSORIES, AGUSTA, BELL	STC SR00646AT, AB 412, AB 412EP, 205, 212, 412	Low Skid Landing Gear Forward Crosstube Identification / Replacement
2010-0106	2010-06-07	ISSOIRE AVIATION	APM 20, APM 30	Landing Gear - Main Landing Gear Leg - Inspection / Replacement
2010-0101-E	2010-06-04	TURBOMECA	ARRIEL 1	Engine - Module M03 (Gas Generator) - Post-TU347 Second Stage Turbine Disc - Reduced Life Limit
CF-2010-16	2010-06-04	BOMBARDIER	DHC-8	Cockpit Windshield Lower Frames - Potential for Corrosion



Publ. number	Issue Date	TC Holder	Type	Subject
US-2010-11-04	2010-06-02	TELEDYNE CONTINENTAL	GTSIO-520, IO-240, IO-346, IO-360, IO-470, IO-520, IO-550, IOF-240, IOF-550, O-240, O-470, TSIO-360, TSIO-470, TSIO-520, TSIO-550, TSIOL-550	Hydraulic Valve Lifters - Identification / Replacement
US-2010-11-05	2010-06-02	AVOX SYSTEMS, B/E AEROSPACE	Type 3HT Oxygen Cylinders, Type 3HT Oxygen Cylinders	Oxygen - Oxygen Cylinders - Inspection / Replacement
US-2010-11-12	2010-06-02	MCDONNELL DOUGLAS	MD11	Fuel - Tail Tank Alternate Fuel Pump Wiring - Modifications
2009-0208R1	2010-06-02	DASSAULT	FALCON 7X	Navigation - Radio-altimeter Lock-up - Operational Procedure
BR-2006-11-01R5	2010-05-31	EMBRAER	ERJ190	Engine Hamilton Sundstrand Low Pressure Check Valve (LPCV) - Periodic Replacement
BR-2009-08-02R1	2010-05-31	EMBRAER	ERJ190	Forward Escape Slides - Replacement / Modification