



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2010-23	2010-07-23	BOMBARDIER	DHC-8	Landing Gear - Main Landing Gear (MLG) - Modification
2010-0151-E	2010-07-23	DYN AVIATION	DR300, DR400	Exhaust - Exhaust Pipes - Inspection
BR-2010-07-03	2010-07-23	EMBRAER	ERJ190	Revision of the Airplane Flight Manual (AFM) - APU Bleed Valve and Cross-bleed Valve
BR-2010-07-02	2010-07-23	EMBRAER	ERJ170	Revision of the Airplane Flight Manual (AFM) - APU Bleed Valve and Cross-bleed Valve
CF-2010-22	2010-07-22	BOMBARDIER	DHC-8	Main Landing Gear Stabilizer Extension Spring
CF-2010-21	2010-07-22	BOMBARDIER	DHC-8	Fuel System - Inadequate Electrical Bonding of the Motive Flow Check Valve
2010-0146	2010-07-22	PIAGGIO	P180	Fuselage - Forward Pressurized Bulkhead - Inspection / Modification
CF-2010-20	2010-07-22	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Horizontal Stabilizer Trim Actuator (HSTA) -Assembly of Discrepant Load Bearing Balls in the HSTA
2010-0148	2010-07-21	AIRBUS	A319, A320, A321	Equipment & Furnishings - DASELL Lavatory Walls - Inspection / Repair
2010-0149	2010-07-21	AIRBUS	A320	Flight Controls - Elevator Aileron Computer (ELAC) System Power Supply - Modification
2010-0144	2010-07-16	AIRBUS	A300-600, A310	Stabilizers - Rudder Side Shell Skin - Inspection
US-2010-14-13	2010-07-15	BOEING	777	Wings - Slat Track Assembly - Inspection / Replacement
2010-0141-CN	2010-07-15	BAE SYSTEMS (OPERATIONS) LTD	BAE146	[Correction] CANCELLATION NOTICE - Placards & Markings - N2 limitations for anti-ice selection - To introduce a placard on the flight deck overhead panel and wiring to inhibit the airbrake auto-retract function.
US-2010-15-01	2010-07-15	BOEING	757, 767, 777	Flightdeck Windows - Electrical Terminal - Inspection / Replacement
2010-0147-E	2010-07-14	EUROCOPTER	SA 330	Rotors - Main Gear Box Oil Cooling Fan - Inspection / Replacement
US-2010-14-20	2010-07-14	MCCAULEY PROPELLER SYSTEMS	4HFR34C653	Propeller - Hubs - Inspection / Replacement
2010-0145	2010-07-14	AIRBUS	A330, A340	Hydraulic Power - High Pressure Manifold Check Valve - Inspection
US-2010-14-17	2010-07-14	BOEING	747	Fuselage - Overwing Intercostal Webs - Inspection / Repair