



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0185-E	2010-09-03	AIRCRAFT INDUSTRIES	L-13 (Blanik)	Prohibition of all flights
2007-0241R4	2010-08-31	PILATUS	PC6	Wing - Wing Strut Fitting - Inspection / Replacement
CF-2010-30	2010-08-31	BOMBARDIER	DHC-8	Cracking of the Nacelle Attachment Fitting(s)
BR-2010-08-03	2010-08-31	EMBRAER	ERJ190	Structural Inspections - Revision of the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness (ICA)
US-2010-17-15	2010-08-30	HAWKER BEECHCRAFT CORPORATION	390	Electric Power - Starter Generators - Inspection / Replacement
US-2010-16-12	2010-08-30	BOEING	777	Engine Exhaust - Oil Scavenge Tube - Inspection / Replacement
2010-0182	2010-08-30	FOKKER SERVICES	F27	Fuel - Fuel Pipes in Engine Nacelles - Inspection / Replacement [Fuel Tank Safety]
2010-0179	2010-08-30	BAE SYSTEMS (OPERATIONS) LTD	JETSTREAM4100	Doors - Upper and Lower Passenger/Crew Door Pin Guides - Inspection / Replacement
2010-0177	2010-08-30	AIRBUS	A319, A320, A321	Fuel System - Additional Centre Tanks Manhole Cover Seal - Replacement
BR-2010-06-03R1	2010-08-30	EMBRAER	EMB135, EMB145	Fuselage - APU Firewall - Inspection / Repair / Replacement
2010-0181	2010-08-27	EUROCOPTER	EC 155	Time Limits/Maintenance Checks - Airworthiness Limitation Section - Amendment / Implementation
CF-2010-29	2010-08-27	BELL CANADA	222, 230, 430	Hydraulic Servo Actuator - Inspection / Rectification / Overhaul
2010-0183-E	2010-08-27	AGUSTA, EUROCOPTER DEUTSCHLAND, Eurocopter UK Ltd, KEYSTONE HELICOPTER, SIKORSKY	AB 139, AW 139, BK 117, EC 135, CAA UK AAN 26529, STC EASA.10028851, STC EASA.R.S.01532, STC EASA.IM.R.S.01256, STC SR02408NY-D, S92	Equipment / Furnishings - Spectrolab Nightsun XP Searchlight - Inspection / Removal
2010-0180	2010-08-27	ISSOIRE AVIATION	APM 20, APM 30	Fuel - Engine Fuel Hoses - Operational Limitation
US-2010-18-52	2010-08-25	MD HELICOPTER	MD900	EASA DECISION NOT TO ADOPT FAA EMERGENCY AD 2010-18-52 - SEE EASA EMERGENCY AD 2010-0172-E
CF-2010-27	2010-08-24	BOMBARDIER	DHC-8	Flight Controls - Elevator Torque Tube - Replacement
CF-2010-28	2010-08-24	BOMBARDIER	DHC-8	Flight Controls - Elevator Power Control Unit - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2010-08-02	2010-08-24	EMBRAER	ERJ190	Pylons - Internal Shear Pin - Replacement
CF-2010-26	2010-08-23	BOMBARDIER	DHC-8	Landing Gear - Door Alternate Release Cable - Modification
2010-0178	2010-08-23	AIRBUS	A300-600, A300-600ST BELUGA, A310	Electrical Power - Wiring Installation at Pylon/Wing Interface - Modification
US-2010-18-51	2010-08-23	MD HELICOPTER	MD900	SUPERSEDED BY FAA EMERGENCY AD 2010-18-52 - EASA DECISION NOT TO ADOPT FAA EMERGENCY AD 2010-18-51 - SEE EASA EMERGENCY AD 2010-0172-E
US-2010-16-11	2010-08-23	MCDONNELL DOUGLAS	MD90	Wings - Main Landing Gear (MLG) Retract Cylinder Support Fitting - Inspection / Installation