



Publ. number	Issue Date	TC Holder	Type	Subject
2011-0103	2011-05-27	CHELTON LTD (COBHAM ANTENNA SYSTEMS)	Tri-Band ELT Antennas	Equipment / Furnishings - Emergency Locator Transmitter (ELT) Antenna - Modification / Replacement
2011-0104	2011-05-27	EUROCOPTER	AS 350, AS 355	Tail Rotor Drive - Tail Gearbox (TGB) Casing Assembly - Inspection / Replacement
2011-0102-E	2011-05-26	DASSAULT	FALCON 7X	Flight Controls - Horizontal Stabilizer Pitch Trim Runaway - Suspension of Flight Operations
2011-0100	2011-05-26	DIAMOND AIRCRAFT INDUSTRIES	DA42, DA42M	Wings - Upper Centre Wing Skin-to-Spar Adhesive Joint - Inspection / Repair
2011-0099	2011-05-26	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Air Conditioning - Front and Rear Discharge Valves Fuselage Skin - Inspection / Repair
31-06-11-05R1	2011-05-26	GULFSTREAM (GALP)	ASTRA, G100	Separation of Main Entry Door (MED) and MED Inflatable Seal Warning Lights.
US-2010-24-13	2011-05-26	BOEING	747	[Correction] Fuel
2011-0096	2011-05-25	BAE SYSTEMS (OPERATIONS) LTD	JETSTREAM4100	Wings - Wing Rear Spar - Inspection / Repair
2011-0101	2011-05-25	SOCATA	TBM700	Flight controls - Aileron Control Cables - Inspection / Reinstallation
CF-2011-06	2011-05-25	BOMBARDIER	DHC-8	Airstair Door - Blocked Water Drainage Path
2011-0097	2011-05-25	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Fuselage - Nose Landing Gear Bay Left Hand Sidewall Stiffeners - Inspection / Repair
2010-0207R1	2011-05-25	EUROCOPTER DEUTSCHLAND	BK 117, EC 135, EC 635	Instruments - Instrument Control Panel - Flight Limitation / Modification
2011-0084	2011-05-24	AIRBUS	A300, A300-600, A300-600ST BELUGA	Electrical Power - Fire Shut-Off Valve (FSOV) Bonding Lead and Wiring - Inspection / Repair
2011-0095-E	2011-05-24	AGUSTA	A119, AW119	Rotors Flight Control - Pilot and Co-pilot Control Box Assemblies - Inspection / Replacement / Modification
2011-0090	2011-05-24	INTERTECHNIQUE	Oxygen masks	[Correction] Oxygen - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement
CF-2011-09	2011-05-24	BOMBARDIER	BD-100	Oxygen Supply System - Deformation of the Pressure Regulator on the Oxygen Cylinder and Regulator Assembly
CF-2011-10	2011-05-24	BOMBARDIER	BD-700	Oxygen Supply System - Deformation of the Pressure Regulator on the Oxygen Cylinder and Regulator Assembly
2010-0235R1	2011-05-23	DIAMOND AIRCRAFT INDUSTRIES	DA40, DA42, DA42M	Doors - Rear Passenger Door Retaining Bracket - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2011-0094	2011-05-23	AERAZUR	Life Jackets	Equipment and Furnishing - Life Jacket Vacuum Bag - Modification
US-2011-09-04	2011-05-23	LOCKHEED	382	Wings - Lower Surface of the Center Wing Box - Inspection
2010-0178R1	2011-05-20	AIRBUS	A300-600, A300-600ST BELUGA, A310	Electrical Power - Wiring Installation at Pylon/Wing Interface - Modification
2011-0093	2011-05-20	CHELTON LTD (COBHAM ANTENNA SYSTEMS)	Tri-Band ELT Antennas	SUPERSEDED BY EASA AD 2011-0103
CF-2011-01R1	2011-05-20	BOMBARDIER	DHC-8	Main Landing Gear Alternate Extension System - Cam Mechanism not in Normal Rested Position
BR-2011-05-04	2011-05-19	EMBRAER	ERJ190	Airworthiness Limitation Section (ALS) of Embraer Model ERJ 190 aeroplane - Revision of the Maintenance Program to include Airworthiness Limitations Inspections updates.
2011-0092	2011-05-18	TECNAM	P92	Structures - Central Beam of Cabin Truss - Inspection / Repair
2011-0091	2011-05-18	EUROCOPTER DEUTSCHLAND	BO 105	Main Rotor Drive - Main Gearbox - Inspection
2011-0089	2011-05-17	Zakład Szybowcowy "Jezow" Henryk Mynarski	SZD-30, SZD-30C	Flight Controls - Airbrakes - Operational Limitations Structures - Wooden Structure and Glue Bonding Joints - Inspection / Repair / Operational Limitations
US-2011-10-02	2011-05-17	BOEING	747	Engine Exhaust - Thrust Reverser Control System - Modification
2010-0244R1	2011-05-17	BOEING	737	Exhaust - Thrust Reverser Inner Wall - Inspection / Repair