



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|----------------------|---------------------------|---|
| 2011-0137 | 2011-07-22 | AIRBUS | A318, A319, A320, A321 | [Correction] Equipment / Furnishings - Passenger Compartment Class Divider / Gas Spring Damper - Inspection / Replacement |
| CF-2011-24 | 2011-07-22 | BOMBARDIER | DHC-8 | Wing to Fuselage Attachment Joints - Barrel Nut Cracking |
| CF-2011-23 | 2011-07-21 | BOMBARDIER | CL-600 (Regional Jet) | Potential Damage to Third Crewman Oxygen System |
| US-2011-12-13 | 2011-07-21 | BOEING | 737 | [Correction] Flight Controls - Stabilizer Takeoff Warning System - Test / Replacement |
| 2011-0138 | 2011-07-20 | AIRBUS | A330, A340 | Navigation - Pitot Probe Quick-Disconnect Union - Torque Check |
| 2011-0135 | 2011-07-20 | AIRCRAFT INDUSTRIES | L-13 (Blanik) | - Prohibition of all flights - Wings - Wing Main Spar - Inspection / Operational Limitation / Operational Records Check |
| 2011-0140 | 2011-07-20 | AGUSTA | AW 139 | Communications - Primus Epic Harnesses Solder Splices - Inspection / Replacement |
| CF-2011-22 | 2011-07-19 | BOMBARDIER | DHC-8 | Electrical - AC Generator Rotor Band Failure |
| 2011-0136R1 | 2011-07-19 | EUROCOPTER | EC225 | Equipment and Furnishings - VHF Antenna for Emergency Flotation Gear Protection - Installation |
| CF-2011-21 | 2011-07-18 | BOMBARDIER | DHC-8 | Fuel System - Chafing of High Pressure Fuel Line |
| TCD-7856-2011 | 2011-07-18 | KOITO INDUSTRIES LTD | Seats and Seating Systems | NOT ADOPTED - EASA DECISION ATTACHED |
| CF-2011-20 | 2011-07-15 | BOMBARDIER | DHC-8 | Power Lever Assembly - Fouling of the United Kingdom Civil Aviation Authority Flight Idle Gate |
| 2011-0134 | 2011-07-14 | AIRBUS | A319, A320 | Fuselage - Keel Beam Side Panels - Inspection |
| 2011-0120R1 | 2011-07-13 | AIRBUS | A318, A319, A320, A321 | Fuselage - Nuts - Inspection / Replacement |
| 2011-0121R1 | 2011-07-13 | AIRBUS | A318, A319, A320, A321 | Wings - Nuts - Inspection / Replacement |
| CF-2011-18 | 2011-07-13 | BOMBARDIER | CL-600 (Regional Jet) | Integrated Drive Generator Wire Chafing in Aft Equipment Bay |
| 2011-0090R1 | 2011-07-13 | INTERTECHNIQUE | Oxygen masks | Oxygen - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement |
| 2011-0132 | 2011-07-12 | PIAGGIO | P180 | Doors - Baggage door - Inspection / Modification |
| 2011-0133 | 2011-07-12 | PIAGGIO | P180 | Landing Gear - Main Landing Gear Actuator - Replacement / Repair |