



Publ. number	Issue Date	TC Holder	Type	Subject
US-71-13-01R1	2012-02-03	LYCOMING	TIO-540	CANCELLED - SEE FAA AD 2011-26-04
2012-0024	2012-02-03	DIAMOND AIRCRAFT INDUSTRIES	DA40	Power Plant - Turbocharger Hose - Inspection/Replacement
2011-0182R1	2012-02-03	TURBOMECA	ARRIUS 2	Engine Fuel & Control - P3 Air Pipe - Inspection / Modification
US-2012-02-07	2012-02-01	GENERAL ELECTRIC	CF6-45, CF6-50	Engines - Low-Pressure Turbine (LPT) Rotor Stage 3 Disks - Inspections / Removal
CF-2011-44R1	2012-02-01	BELL CANADA	206	Main Rotor Blades - Life Limitation
2012-0022	2012-02-01	EUROCOPTER	AS 355	Starting - Starter Generator - Check / Replacement / Modification
2011-0155R1	2012-01-31	AIRBUS	A318, A319, A320, A321	[Correction] Time Limits and Maintenance Checks - Fuel Airworthiness Limitations - ALS Part 5 - Amendment
CF-2012-08	2012-01-31	BOMBARDIER	DHC-8	Power Lever Friction Brake Assembly Discrepancy
CF-2012-07	2012-01-30	BOMBARDIER	DHC-8	Cockpit "Engine Fire, Check Fire Detect" Warning and "FUEL OFF" Handle Lights Failure to Reset
2012-0020	2012-01-30	AIRBUS	A330	Time Limits and Maintenance Checks - Ageing Systems Maintenance - ALS Part 4 - Amendment
CF-2012-06	2012-01-30	BOMBARDIER	CL-600 (Regional Jet)	Bleed Leak Detection System - Inability to Detect a Cracked/Ruptured Bleed-Air Duct
2012-0021	2012-01-30	AIRBUS	A340	Time Limits and Maintenance Checks - Ageing Systems Maintenance - ALS Part 4 - Amendment
US-2012-01-06	2012-01-27	BOEING	767	Equipment and Furnishings - Forward Cargo Compartment - Modifications
US-2012-01-11	2012-01-26	CIRRUS	SR22T	PowerPlant - Air Box Flange Welds and Slots - Induction System Air Box Seals - Inspection / Modification / Installation
2012-0017	2012-01-26	AIRBUS	A380	Fuel - Feed Tank 1 and/or 4 Main and Standby Pump Fault Light Flickering - Operational Procedure / Replacement
US-2012-01-09	2012-01-26	BOEING	757	Equipment and Furnishings - Off-wing Escape Slide Systems - Placards - Modification / Installation
2012-0019-E	2012-01-26	BRP-POWERTRAIN GMBH	912 S, 914 F	Engine Oil - Oil Pump and Attachment Bolts - Inspection
2012-0016	2012-01-26	AIRBUS	A310	Wings - Fuel Access Panels - Replacement / Modification
2012-0018	2012-01-25	CEAPR	DR 200, DR 220, DR 221, DR 250, DR 253, DR 300, DR 315, DR 340, DR 360, DR 380, DR 400, HR 100, R 1180, R 3000	Oil System - Oil Lines - Replacement
US-2012-01-10	2012-01-24	GENERAL ELECTRIC	CF34-10	Turbine / Turboprop Engine - Center Vent Duct (CVD) & Fan Drive Shaft - Inspection / Removal
US-2011-25-03	2012-01-23	LEARJET	45	NOT ADOPTED - SEE EASA AD 2012-0014



Publ. number	Issue Date	TC Holder	Type	Subject
2012-0012	2012-01-23	AIRBUS	A318, A319, A320, A321	Flight Controls - Flap Interconnecting Strut - Identification / Modification / Replacement
2011-0236	2012-01-23	AGUSTAWESTLAND	A109	[Correction] Landing Gear - Main Landing Gear (MLG) Actuator Bracket Attachment Bolts - Replacement / Inspection
2012-0014	2012-01-23	LEARJET	45	Time Limits / Maintenance Checks - Main Landing Gear Actuator End Cap - Reduced Life Limit
2012-0015	2012-01-23	AIRBUS	A330, A340	Landing Gear - Main Landing Gear Bogie Beam - Inspection / Repair / Modification