



Publ. number	Issue Date	TC Holder	Type	Subject
2012-0239	2012-11-09	FOKKER SERVICES	F28	Placards and Markings - Passenger Compartment Exit Signs - Replacement
2012-0238	2012-11-09	FOKKER SERVICES	F27	Placards and Markings - Passenger- and Cargo Compartments Exit Signs - Replacement
2012-0237	2012-11-09	ROLLS-ROYCE PLC	RB211 TRENT 500	Engine - Low Pressure Fuel Tubes, Clips and Fuel Oil Heat Exchanger Mounts - Inspection
2011-0091R2	2012-11-08	EUROCOPTER DEUTSCHLAND	BO 105	Main Rotor Drive - Main Gearbox - Inspection
2012-0233	2012-11-07	AIRBUS	A300	Time Limits / Maintenance Checks - Ageing System Maintenance - Airworthiness Limitations - Introduction
2012-0235	2012-11-07	AIRBUS	A340	Fuel - Fuel Control & Monitoring Computer - Test / Modification
CF-2012-27	2012-11-06	BOMBARDIER	DHC-8	Cracking of the Nacelle Lower Longeron
2012-0234	2012-11-06	ROLLS-ROYCE DEUTSCHLAND	Tay	Engine - Low Pressure Compressor / Rotor Blades - Inspection
2012-0191R1	2012-11-06	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Time Limits / Maintenance Checks - Nose Landing Gear Main Fitting Life Limitation - Implementation
US-2012-21-01	2012-11-05	MD HELICOPTERS INC (MDHI)	MD900	Main Rotor - Main Rotor (MR) Lower Hub Assembly - Inspection / Replacement
2011-0200-CN	2012-11-05	MD HELICOPTERS INC (MDHI)	MD900	CANCELLATION NOTICE - Main Rotor - Main Rotor (MR) Lower Hub Assembly - Inspection / Replacement
2012-0224	2012-11-05	AIRBUS	A340	[Correction] Nacelles / Pylons - Outboard Pylon Extension Fairing / Shutter Flap - Inspection / Repair / Replacement
2012-0231	2012-11-02	TURBOMECA	MAKILA 1	Engine Indicating - N2 Sensor Harness - Replacement
CF-2012-26	2012-11-01	BOMBARDIER	CL-600 (Regional Jet)	Flap Actuator Seal Replacement
US-2012-21-13	2012-10-31	BOEING	DC-9, MD-88	Wings - Stringer 11 Outboard Flap - Inspections / Repair
BR-2012-10-01	2012-10-31	EMBRAER	ERJ170	[Correction] Airworthiness Limitation Section (ALS) of Embraer Model ERJ 170 aeroplane - Maintenance Plan New Revision - Inspections
US-2012-19-11	2012-10-31	BOEING	737	Air Conditioning - Cabin Altitude Pressure Switch - Aural Warning Module (AWM) - Installation / Replacement
US-2012-20-06	2012-10-31	BOEING	737	Flight Controls - Aft Attach Lugs for the Elevator Tab Control Mechanism - Inspection / Replacement
US-2012-20-01	2012-10-31	BOEING	737	Fuselage Station 908 Area - Inspection / Testing / Modification
US-2012-21-10	2012-10-31	BOEING	777	Flight Controls - Rudder Power Control Unit (PCU) - Replacement
2012-0232-E	2012-10-31	AIRBUS	A300-600, A310	Equipment / Furnishings - Portable Oxygen Cylinder in Overhead Stowage - Inspection / Replacement
2012-0229	2012-10-31	AIRBUS	A300, A300-600	Fuselage - Frame Base Fitting between Frames 41 and 46 Area 2 - Inspection
US-2012-21-02	2012-10-30	BOEING	767	Wing Leading Edge Area Fluid Drain Path - Modification
2012-0230	2012-10-30	ROLLS-ROYCE DEUTSCHLAND	BR700-715	Engine - High Pressure Compressor Rotor Disc Assembly - Removal



Publ. number	Issue Date	TC Holder	Type	Subject
2012-0085R5	2012-10-30	EUROCOPTER DEUTSCHLAND	EC 135, EC 635	Main Rotor System - Main Rotor Hub - Inspection / Replacement
2012-0227	2012-10-29	EUROCOPTER	AS 365, EC 155, SA 365	Tail Rotor - Tail Rotor Hub - Inspection / Replacement
2012-0228-E	2012-10-29	ALENIA AERMACCHI S.P.A.	F260, S208	Powerplant - Propeller Governor Idler Gear Shaft - Inspection
2012-0226	2012-10-29	AIRBUS	A380	Electric and Electronic Common Installation - EN6049 Sleeve / Backshell Tightening in Landing Gear Bays - Inspection / Rework