



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0201R1	2012-12-21	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Landing Gear - Main Landing Gear Shock Absorber Lower Attachment Pins - Inspection / Replacement
2012-0267	2012-12-21	AIRBUS	A380	Passenger Oxygen - Oxygen Distribution Pressure Line and Container Manifolds - Inspection
2012-0272-CN	2012-12-21	ROLLS-ROYCE PLC	RB211 TRENT 700	CANCELLED: Engine - High Pressure Compressor to High Pressure Turbine Joint Bolts - Inspection
2012-0273	2012-12-21	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine - Intermediate Pressure Compressor Rear Stub Shaft Piston Ring - Inspection
2012-0254R1	2012-12-21	INTERTECHNIQUE	Oxygen masks	Oxygen - Flight Crew Oxygen Mask Regulator - Identification / Operational Procedure / Replacement
2012-0271	2012-12-21	AIRBUS	A330	Auto Flight / Flight Controls - Flight Control Primary Computer - Modification / Replacement
2012-0274	2012-12-21	AIRBUS	A330, A340	Doors - Forward and Aft Cargo Compartment Doors - Inspection / Repair
2012-0270	2012-12-20	BRITTEN-NORMAN AIRCRAFT LTD	BN2A (Islander), BN2A Mark III (Trislander)	Fuel System - Tank Filler Cap and Receptacle - Inspection / Replacement
2012-0268	2012-12-19	PILATUS AIRCRAFT LTD	PC-6	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment / Implementation
2012-0269	2012-12-19	DIAMOND AIRCRAFT INDUSTRIES	DA42, DA42M	Power Plant - Air Intake / Induction Filter Icing - AFM Revision
2012-0263	2012-12-18	EUROCOPTER DEUTSCHLAND	BK 117	Lighting - Flight Control Display System Wire Harness - Modification
2012-0265	2012-12-18	ROLLS-ROYCE PLC	RB211-535	Engine - Critical Parts - Life Limits
2012-0266	2012-12-18	ROLLS-ROYCE PLC	RB211-535	Engine - Low Pressure Turbine Stage 2 Discs - Life Limits
US-2012-25-07	2012-12-17	GULFSTREAM AEROSPACE CORPORATION	GIV	Flight Controls - Flap/Stabilizer Electronic Control Unit (FSECU) - Aircraft Flight Manual (AFM) - Modified System Power-on Self test (SPOST) of the FSECU / Revision
2012-0236R1	2012-12-17	AIRBUS	A318, A319, A320, A321	Navigation - Angle of Attack (AoA) Sensors - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2012-31	2012-12-17	BOMBARDIER	BD-700	Passenger Oxygen System - Incorrect Length of Oxygen Dispensing Unit Lanyards
CF-2012-33	2012-12-17	BOMBARDIER	DHC-8	In-Flight Operation of Propellers In Beta Range
CF-2012-32	2012-12-17	BOMBARDIER	BD-700	Ice Protection System - Inability to Detect Number 2 Pitot Static Probe Heater Failure
CF-2012-30	2012-12-17	BOMBARDIER	CL-600 (Challenger)	Air Data Computer - Erroneous Airspeed and Altitude Indications
US-2012-23-14	2012-12-17	BOEING	737	Aft Drain Mast Fuselage Skin, Channels, Fillers and Bonding Strap - Inspection / Repair
2012-0264-E	2012-12-17	AIRBUS	A318, A319, A320, A321	Airplane Flight Manual - Blocked Angle of Attack Sensor - Operational Procedure
2012-0262	2012-12-14	AGUSTAWESTLAND	AB 139, AW 139	Landing Gear - Nose Landing Gear Arm Pin Installation - Inspection
2012-0261	2012-12-14	MD HELICOPTERS INC (MDHI)	MD900	Main Rotor - Main Rotor Blade Retention Bolts - Inspection / Replacement (Life Limit)
US-2012-25-03	2012-12-14	BOEING	757	Ice and Rain Protection - Windshields - Inspection / Repair
US-2012-24-10	2012-12-13	BOEING	747	Air Conditioning - Integrated Display Unit (IDU) - Software Update
2009-0114R1	2012-12-13	DOWTY PROPELLERS	R408/6-123-F/17	[Correction] Propellers - Backplate Assembly - Sealant Application
US-2012-23-01	2012-12-13	CESSNA AIRCRAFT COMPANY, SIERRA INDUSTRIES, LTD.	402, 414, CAA UK AAN 17341 , LBA EMZ 0228/2032a , STC SA892NW, STC SA927NW	Wings - Flap Control System - Inspection / Repair
CF-2012-07R1	2012-12-12	BOMBARDIER	DHC-8	Cockpit "Engine Fire, Check Fire Detect" Warning and "FUEL OFF" Handle Lights Failure to Reset
US-2012-23-11	2012-12-12	ERICKSON AIR-CRANE	S-64	Tail Boom Transition Fittings, Bulkhead Assembly, and Pylon - Inspection
2012-0260	2012-12-11	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine Oil System - Fuel-to-Oil Heat Exchanger - Replacement [Time Between Overhaul]