



Publ. number	Issue Date	TC Holder	Type	Subject
2013-0129	2013-06-21	AIRBUS	A318, A319, A320, A321	Airborne Auxiliary Power - Auxiliary Power Unit Exhaust Tailpipe - Modification
2013-0130	2013-06-21	EUROCOPTER	AS 355	Time Limits / Maintenance Checks - Airworthiness Limitations - Revision
US-2013-10-01	2013-06-20	SPECTROLAB, INC.	Searchlights	Equipment / Furnishings - Spectrolab Nightsun XP Searchlight - Inspection / Removal / Replacement
2010-0237-CN	2013-06-20	AGUSTAWESTLAND, EUROCOPTER DEUTSCHLAND, Eurocopter UK Ltd, KEYSTONE HELICOPTER, SIKORSKY	AB 139, AW 139, BK 117, EC 135, CAA UK AAN 26529, STC EASA.1002885 1, STC EASA.R.S.015 32, STC EASA.IM.R.S.0 1256, STC SR02408NY-D, S-92	CANCELLED: Equipment / Furnishings - Spectrolab Nightsun XP Searchlight - Inspection / Removal / Replacement
2013-0081R1	2013-06-20	EUROCOPTER	AS 332, EC225, SA 330	Rotor Flight Controls - Tail Rotor Control Turnbuckle - Inspection / Replacement
CF-2013-16	2013-06-19	BOMBARDIER	DHC-8	AC Feeder Cables not Clamped to Hydraulic Lines - Inspection / Rectification
CF-2013-15	2013-06-19	BOMBARDIER	DHC-8	In-Flight Operation of Propeller in Beta Range
US-2013-12-02	2013-06-18	ENGINE ALLIANCE LLC	GP7200	High Pressure Compressor Stage 6 Disks - Inspection / Replacement
US-2013-11-16	2013-06-18	AVIATION PARTNERS INC., HAWKER BEECHCRAFT CORPORATION	EASA STC 10015403, STC EASA.IM.A.S.0 1113, STC ST01411SE, BAe/BH/DH/H S.125, Hawker	Wings - Aileron Oscillation - AFM Change / Placards Installation
2013-0128	2013-06-17	DASSAULT	FALCON 7X	Landing Gear - Nose Wheel Steering - Airplane Flight Manual Change
US-2013-11-14	2013-06-17	BOEING	777	Nacelles / Pylons - Strut Forward Dry Bay - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
US-2013-10-04	2013-06-14	PIPER AIRCRAFT INC.	PA-31 (Navajo)	Engine Exhaust - Exhaust System Downstream - Inspection
CF-2013-13	2013-06-11	BOMBARDIER	CL-600 (Regional Jet)	Rudder Controls - Yaw Damper Uncommanded Movement
2013-0127	2013-06-11	AIRBUS	A340	Time Limits and Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment
US-2013-11-05	2013-06-10	BELL	214	Tail Rotor Drive Bearing - Inspection / Replacement
2010-0132R1	2013-06-10	AIRBUS	A330	Fuel - Main Fuel Pump System Water Scavenge System - Deactivation
CF-2013-14	2013-06-10	BOMBARDIER	CL-600 (Regional Jet)	Horizontal Stab Trim Actuator (HSTA) - Loose Bolts on the Spur Gear - Replacement