



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2012-31R1	2013-09-27	BOMBARDIER	BD-700	Passenger Oxygen System - Incorrect Length of Oxygen Dispensing Unit Lanyards
2013-0238	2013-09-27	MECAER AVIATION GROUP SpA	NH-300C	Tail Rotor Drive - Drive Shaft Splined Fittings - Inspection
CF-2013-26	2013-09-27	BELL CANADA	430	Main Rotor Hub to Main Rotor Mast Attachment - Bolt Life limitation
2013-0233	2013-09-26	AIRBUS	A380	Fuselage - Belly Fairing Structure - Inspection / Repair
2013-0237-E	2013-09-26	EUROCOPTER	AS 332, EC225	Equipment and Furnishing - Emergency Flotation Gear - Inspection
US-2013-15-18	2013-09-26	LOCKHEED MARTIN CORPORATION	L-1011 (Tristar)	Structures / Doors / Fuselage / Wings - Inspection / Repair
2013-0236	2013-09-25	AQUILA AVIATION GmbH	AT01	Fuel - Fuel Tank Opening / Bore Hole Sealing - Inspection / Repair
2011-0001R1	2013-09-25	AIRBUS	A318, A319, A320, A321	Indicating & Recording Systems - Flight Warning Computers - Replacement
2013-0235	2013-09-25	MECAER AVIATION GROUP SpA	NH-300C	Rotor Drive - Main Rotor Thrust Bearing Spacer Tube - Inspection / Replacement
2013-0232	2013-09-24	AIRBUS	A300-600, A300-600ST BELUGA	Wings - Top Skin at Front Spar between Ribs 1 and 7 - Inspection / Modification
2013-0231	2013-09-24	ROLLS-ROYCE DEUTSCHLAND	BR700-715	Engine - Low Pressure Compressor Case / Ice Impact Panels - Replacement
2013-0234	2013-09-24	AIRBUS	A300, A300-600	Wings - Flap Beam Base - Inspection / Replacement
US-2013-15-17	2013-09-24	BOEING	737	Fuel - Engine Fuel Suction Feed Capability of the Fuel System - Inspection
2008-0208R2	2013-09-24	AIRBUS	A310	Wings - Centre Wing Bottom Skin at Rib 1 - Inspection
BR-2013-09-01	2013-09-24	EMBRAER	EMB505	Landing Gear - Brake Assembly - Inspection
2013-0230	2013-09-24	AIRBUS	A300, A300-600	Wings - Centre Wing Bottom Skin at Rib 1 - Inspection
US-2013-16-24	2013-09-23	BOEING	747	Fuselage - Skin Lap Joint - Inspection / Repair
2013-0226	2013-09-23	AIRBUS	A320	Wings - Center Section / Pressurized Floor Fittings at Frame 36 Junction - Inspection
2013-0229	2013-09-23	ROLLS-ROYCE DEUTSCHLAND	BR700-710	Engine Fuel and Control - Fuel Metering Unit - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2013-0227	2013-09-23	SOCATA	TBM 700	Landing Gears - Nose and Main Landing Gear Actuators - Inspection / Replacement
2013-0228-E	2013-09-23	EUROCOPTER DEUTSCHLAND	EC 135, EC 635	Rotor Flight Controls - Main Rotor Actuator - Identification / Replacement
2013-0225-E	2013-09-20	AGUSTAWESTLAND	A109, A119, AW109SP, AW119	Tail Rotor - Tail Rotor Drive Shaft Line Nut - Inspection
2013-0222	2013-09-19	FOKKER SERVICES	F28	Time Limits / Maintenance Checks - Maintenance Requirements - Implementation
2010-0044R1	2013-09-19	AIRBUS	A340	Exhaust - Thrust Reverser Actuation System Doors - Replacement
2013-0223	2013-09-19	ROLLS-ROYCE PLC	RB211 TRENT 800	Engine - Low Pressure Turbine Bearing Support and Exhaust Case Assembly - Inspection / Replacement
2013-0224	2013-09-19	DIAMOND AIRCRAFT INDUSTRIES	DA42, DA42M	Electrical Power - Alternator Fail Indication - Modification
2013-0221	2013-09-19	AIRBUS	A300-600	Wings - Top Skin Centre Spar Joint between Ribs 1 and 7 - Inspection / Repair
US-2013-13-01	2013-09-18	PIPER AIRCRAFT INC.	PA-46 (Malibu)	[Correction] Fuel vent Valves - Inspection / Modification / Replacement
2009-0070R2	2013-09-18	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Fuselage - External Forward Fuselage - Inspection / Repair
US-2013-17-08	2013-09-18	BOEING	747	Fuselage - Frame Segments - Inspection / Repair
2013-0096R1	2013-09-18	ROLLS-ROYCE PLC	TRENT 1000	Engine - Intermediate Pressure Turbine Blades - Inspection
2013-0220	2013-09-18	AIRBUS	A300, A300-600, A310	Fuselage - SRM Repairs on Floor Cross Beams Flange at Frame 11 and Frame 12A - Inspection / Repair
2013-0218	2013-09-17	EUROCOPTER	AS 365, SA 365	Main Rotor Hub - Frequency Adapter / Torque Value - Adjustment / Modification
2013-0216	2013-09-17	AIRBUS	A300, A300-600, A310	Nacelles / Pylons - Pylon Lower Spar between Ribs 9 and 10 - Inspection
2013-0219	2013-09-17	AIRBUS	A330, A340	Fuselage - Trimmable Horizontal Stabilizer Support Struts - Inspection / Replacement
2013-0217-E	2013-09-16	SOLO KLEINMOTOREN GmbH	2350	Engine - Operation Restriction
2013-0214	2013-09-16	ROLLS-ROYCE PLC	RB211 TRENT 500	Engine - Low Pressure Compressor Blade Leading Edge Profile - Rework / Restoration



Publ. number	Issue Date	TC Holder	Type	Subject
2013-0215	2013-09-16	BRITTEN-NORMAN AIRCRAFT LTD	BN2A (Islander), BN2A Mark III (Trislander), BN2B (Islander)	Engine Controls - Engine Control Cables - Inspection / Replacement
US-2013-17-07	2013-09-16	GENERAL ELECTRIC	GE90	Engine - High-Pressure Turbine Stator Shrouds - Inspection / Removal