



Publ. number	Issue Date	TC Holder	Type	Subject
US-2013-24-12	2013-12-06	BOEING	747	Powerplant. Forward Engine Mount Barrel Nuts and Bolts - Repetitive Ultrasonic or Dye Penetrant Inspections
2013-0289-E	2013-12-06	EUROCOPTER R DEUTSCHLAND	EC 135, EC 635	Fuselage - Rear Structure / Ring Frame - Inspection
2012-0200R1	2013-12-06	AIRBUS	A380	Doors - Upper Deck Door Visual Indication Mechanism - Replacement
US-2013-24-11	2013-12-06	BOEING	747	Fuselage - Fuselage Skin Panel, Fastener and Doubler - Repetitive Inspections / Repair
2013-0288	2013-12-06	AIRBUS	A318, A319, A320, A321	Landing Gear - Main Landing Gear Door Actuator - Monitoring / Inspection / Replacement / Modification
2013-0287	2013-12-05	EUROCOPTER R	AS 350, EC 130	Rotorcraft Flight Manual - Engine Digital Electronic Control Unit Emergency Procedure - Amendment
US-2013-21-07	2013-12-05	BOEING	727	Stabilizers - Web of the Horizontal Stabilizer Center Section Rear Spar - Inspection / Modification / Repair
US-2013-24-07	2013-12-05	BOEING	707, 720	Fuel - Fuel Tank Access Doors - Inspection / Replacement. Airworthiness Limitations Section Maintenance Programme Review - Modification.
US-2013-23-18	2013-12-05	GENERAL ELECTRIC	GE90	Engine - Variable Bypass Valve (VBV) Actuator Fuel Supply Tube - Replacement
US-2013-19-24	2013-12-04	MD HELICOPTERS INC (MDHI)	369	Tail Rotor Blades and Pitch Horns - Life Limit Reduction / Inspection / Replacement
US-2013-22-15	2013-12-04	SIKORSKY	S-76	Main Rotor - Main Rotor Head - Inspection
2013-0285	2013-12-04	AIRBUS	A340	Wings - Center Wing Box / Keel Angle Fitting and Forward Lower Shell Junction - Inspection
US-2013-20-16	2013-12-04	MD HELICOPTERS INC (MDHI)	MD900	NOT ADOPTED - EASA DECISION ATTACHED
US-2013-23-14	2013-12-04	GENERAL ELECTRIC	GENx	Engine - Life-Limited Parts (LLPs) - Adjustment
2013-0286	2013-12-04	AIRBUS	A300-600, A300-600ST BELUGA	Nacelles and Pylons - Rib 5 Lower Area - Inspection / Replacement
2013-0277R1	2013-12-04	AIRBUS	A318, A319, A320, A321	Wings - Outer Wing Refuelling Aperture Electrical Bonding - Inspection / Modification
US-2013-22-03	2013-12-02	BOEING	727	Fuel Tank Access Doors - Inspection / Maintenance Program - Revision
2013-0284-E	2013-12-02	EUROCOPTER R	AS 350	Rotor Drive - Hydraulic Pump - Inspection / Replacement
CF-2013-38	2013-11-29	BOMBARDIER	DHC-8	Design Deficiency of the Nose Wheel Steering Control Unit



Publ. number	Issue Date	TC Holder	Type	Subject
US-2013-23-07	2013-11-29	ERICKSON AIR-CRANE	S-64	Main Rotor - Main Rotor Blades - Inspection / Replacement
CF-2013-37	2013-11-28	BOMBARDIER	CL-600 (Regional Jet)	Aft Baggage Bay Door - Non-Conforming Stop Fittings and Striker Plates
CF-2005-11R2	2013-11-28	PRATT & WHITNEY CANADA	PW100	Replacement of Fuel Manifold Adapter Assemblies
US-2013-23-15	2013-11-28	BOEING	747	Fuselage - Fuselage Skin - Inspection
2013-0281	2013-11-27	EUROCOPTER	AS 350, AS 355	Lights - Position Strobe Light - Inspection / Deactivation / Modification
2013-0282-E	2013-11-27	AGUSTAWES TLAND	AB 212, AB 412, AB 412EP	Rotor Drive(s) - Lubricating System / Oil Outlet Hose - Inspection
2013-0270R1	2013-11-27	AIRBUS	A330, A340	Stabilizers - Rudder Side Panel Along the Z-Profile - Inspection
2013-0275R1	2013-11-27	AGUSTAWES TLAND, BELL HELICOPTER TEXTRON CANADA (BHTC), BELL HELICOPTER TEXTRON Inc. (BHTI), EUROCOPTER R, EUROCOPTER R DEUTSCHLAN D, MD HELICOPTER S INC (MDHI), SIKORSKY	AB 139, AB 412, AW 139, AW109SP, 429, 430, 212, 214, 214ST, 412, AS 332, AS 365, EC225, BK 117, EC 135, EC 635, MD900, S-61, S-76, S-92	Equipment / Furnishing - Hoist - Test / Replacement
US-2013-24-01	2013-11-27	BOEING	747, 787	Power Plant - Ice Crystal Icing (ICI) Conditions at high Altitudes - Inspection Airplane Flight Manual (AFM) - Revision
2013-0278	2013-11-26	AIRBUS	A318, A319, A320, A321	Oxygen - Crew Oxygen / Oxygen Pipe Corrosion - Inspection
2013-0279	2013-11-26	TECHNIFY MOTORS	TAE125 (Centurion 2.0)	Engine Fuel & Control - High Pressure Fuel Pump - Replacement
2013-0280	2013-11-26	ATR	ATR42, ATR72	Equipment / Furnishing - Type III Emergency Exit Door - Inspection / Modification



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2013-35	2013-11-25	BOMBARDIER	DHC-8	Engine Fuel Feed Ejector Pump Swing Arm Assembly Failure