



Publ. number	Issue Date	TC Holder	Type	Subject
2014-0037	2014-02-14	AGUSTAWESTLAND	A109, AW109SP	Main Rotor Drive - Engine to Transmission Drive Shaft Nuts - Inspection / Replacement
2014-0038	2014-02-14	GUIMBAL, HELICOPTERES	CABRI	Powerplant - Engine Cooling Fan - Inspection / Modification
CF-2014-09	2014-02-14	PRATT & WHITNEY CANADA	PW150	Engine High Pressure Fuel Line Fretting
2013-0266R1	2014-02-14	AIRBUS	A380	Wings - Cruciform Fitting Frame 56 - Inspection / Modification
2012-0230R1	2014-02-12	ROLLS-ROYCE DEUTSCHLAND	BR700-715	Engine - High Pressure Compressor Rotor Disc Assembly - Removal
US-2013-24-04	2014-02-11	LEARJET, INC.	60	Fuel Crossflow Tube - Inspection / Repair / Replacement
2014-0036	2014-02-11	TURBOMECA	ARRIEL 1, ARRIEL 2	Engine - Accessory Gear Box (M01) - 41/23 Tooth Bevel Gear Assembly - Check / Replacement
2014-0035	2014-02-11	BAE SYSTEMS (OPERATIONS) LTD	ATP	Electrical Power - Brandenburg Static Inverter Power Supply - Modification
US-2014-01-05	2014-02-10	BOEING	737	Fuselage - Stringer Splices and Butt Joints Cracks - Inspection / Repair
2013-0089R1	2014-02-06	AIRBUS	A380	Hydraulic Power - Hydraulic Power Accumulator - Replacement
2014-0027R1	2014-02-05	DASSAULT AVIATION	Falcon 2000	Equipment / Furnishings - Tie-Downs in Forward Servicing Compartment - Inspection / Removal
2012-0267R1	2014-02-05	AIRBUS	A380	[Correction] Passenger Oxygen - Oxygen Distribution Pressure Line and Container Manifolds - Inspection
CF-2014-07	2014-02-05	BOMBARDIER	CL-600 (Regional Jet)	Cracking of Skin Panels and Skin Splice Joints and Angles at Stringers 6 and 20 Between Fuselage Station 409.00 and 589.00
2014-0034	2014-02-05	AIRBUS	A300-600, A300-600ST BELUGA, A310	Electrical Power - Wing Electrical Installation - Modification
2014-0032	2014-02-04	BAE SYSTEMS (OPERATIONS) LTD	ATP	Powerplant - Engine Side Aft Isolators - Inspection / Replacement
2014-0033	2014-02-04	AIRBUS	A330, A340	Stabilizers - Rudder side shell sandwich repair - Inspection
2014-0031	2014-02-04	ROLLS-ROYCE PLC	RB211 TRENT 700	Engine - Low Pressure Compressor Blades - Inspection / Replacement
US-2014-02-03	2014-02-03	HAWKER BEECHCRAFT CORPORATION	1900 (Airliner)	Flight Controls - Secondary Elevator Bob-Weight Stop Bolt - Inspection / Installation