



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2015-02-02	2015-02-27	EMBRAER	ERJ-190	Pneumatic - Low-Stage Bleed Check Valve and the Controller Operational Program of the Air Management System (AMS) - Replacement
2015-0035-E	2015-02-27	AGUSTAWESTLAND	A109, A119, AW119	Tail Rotor - Pitch Control Link Assembly - Inspection / Replacement
2015-0034-E	2015-02-27	STEMME	ASP, TSA-M	Flight Controls - Aileron, Speed Brake and Flap Control Systems - Modification
US-2015-04-05	2015-02-26	SIKORSKY	S-76	Tail Rotor Drive - Tail Rotor Drive Shaft (TDS) Flange-to-Shaft Attachment Hardware - Inspection
2014-0047	2015-02-26	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	[Correction] Wings - Fixed Wing Leading Edge and Front Spar Structure - Inspection / Repair
2014-0217R1	2015-02-26	AIRBUS	A318, A319, A320, A321	Auto Flight / Instruments - Stop Rudder Input Warning - Installation / Activation
2015-0032	2015-02-24	FOKKER SERVICES	F28	Time Limits / Maintenance Checks - ALS Part 3 - Fuel Airworthiness Limitations - Implementation
2015-0031	2015-02-24	FOKKER SERVICES	F27	Time Limits / Maintenance Checks - ALS Part 3 - Fuel Airworthiness Limitations - Implementation
2015-0033-E	2015-02-24	AIRBUS HELICOPTERS	AS 350 / EC 130	Fuselage - Tail Boom / Fenestron Junction Frame - Inspection
2015-0029	2015-02-24	FOKKER SERVICES	F27	Fuel - Fuel Airworthiness Limitations - Implementation
2015-0030	2015-02-24	FOKKER SERVICES	F28	Fuel - Fuel Airworthiness Limitations - Implementation
2015-0028	2015-02-24	AIRBUS	A330, A340	Doors - Potable Water Service Panel Access Door Latching Mechanism - Modification
2010-0188R1	2015-02-23	ROLLS-ROYCE PLC	RB211 TRENT 800	Engine - Fan Case Low Pressure Fuel Tubes and Clips - Inspection / Replacement
2015-0027	2015-02-20	FOKKER SERVICES	F28	Time Limits / Maintenance Checks - ALS Part 1 - Certification Maintenance Requirements - Implementation
US-2015-03-04	2015-02-20	BOEING	747	Fuselage - Lower Forward Corner of the Main Entry Door - Repetitive Inspections / Repair / Modification
2015-0024	2015-02-19	FOKKER SERVICES	F28	Fuselage - Skin Connection Angle and Pressure Bulkhead - Inspection
2015-0026	2015-02-19	AIRBUS	A319, A320	Wings - Wing Bottom Skin at Main Landing Gear Rib 5 - Inspection
2014-0249R1	2015-02-18	ROLLS-ROYCE PLC	RB211-535	Time Limits / Maintenance Checks - Engine Critical Parts - Reduction of Cyclic Life Limits
2015-0025-E	2015-02-18	AGUSTAWESTLAND	A109	Rotor(s) - Main Rotor Blades - Identification / Replacement
2015-0023-E	2015-02-18	FFA AIRCRAFT BRAVO AG	AS202	Fuselage - Upper Forward Fuselage Stringers - Inspection / Repair
US-2015-02-26	2015-02-18	BOEING	737	Fuselage - Seat Track Link Assembly - Modification / Repair / Replacement
BR-2015-02-01	2015-02-16	EMBRAER	ERJ-190	SUPERSEDED BY ANAC BRAZIL AD 2015-02-02
2015-0022	2015-02-16	AGUSTAWESTLAND	AW109SP	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation