



Publ. number	Issue Date	TC Holder	Type	Subject
2015-0053	2015-03-27	BAE SYSTEMS (OPERATIONS) LTD	ATP	Fuel - Rigid Fuel Pipes - Replacement
2015-0052-E	2015-03-27	SOLO KLEINMOTOREN GmbH	2350	Engine - Operation Restriction
2015-0054	2015-03-27	AGUSTAWESTLAND	A109, AW109SP	Tail Rotor Drive - Drive Shaft Assembly - Inspection / Replacement
GA8-8-Amdt1	2015-03-26	GIPPSLAND	GA8	Engine Mount Fire Seal Washer
BR-2015-03-01	2015-03-25	EMBRAER	EMB-135, EMB-145	Fuel - Electric Fuel Pump Harness - Inspection / Installation
2014-0188R2	2015-03-25	AGUSTAWESTLAND, AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND	AB 212, AB 412, AB 412EP, SA 330 / AS 332 / EC 225, SA 365/366 / AS 365 / EC 155, MBB-BK 117	Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual (Supplement)
2015-0051	2015-03-25	AIRBUS	A318, A319, A320, A321	Nacelles / Pylons - Aft Pylon Moveable Fairing Rib 5 - Inspection / Repair
US-2015-05-08	2015-03-24	LOCKHEED MARTIN CORPORATION	382 (Hercules)	Wings - Upper and Lower Rainbow Fittings - Repetitive Inspections / Replacement
2015-0050	2015-03-23	ROLLS-ROYCE DEUTSCHLAND	Tay	Engine - Stages 2 and 3 Low Pressure Turbine Discs - Inspection / Replacement
2014-0243R1	2015-03-23	ROLLS-ROYCE PLC	RB211 TRENT 700	[Correction] Engine Fuel and Control - Low Pressure Fuel Tubes and Clips, Fuel Oil Heat Exchanger Mounts - Inspection / Replacement
2014-0013R1	2015-03-19	PIAGGIO	P166, P180	Propellers - Blades - Inspection / Repair
CF-2015-04	2015-03-19	BOMBARDIER	BD-100	Navigation - Pitot-Static Probe Heater Failure
2015-0048	2015-03-17	AIRBUS HELICOPTERS	SA 365/366 / AS 365 / EC 155	Equipment / Furnishing - External Life Raft - Modification
2015-0049	2015-03-17	TURBOMECA	ARRIUS 2	Oil - Oil Pump Drive Link / Lubricating Device - Inspection
2015-0046	2015-03-16	AllStar PZL Glider	SZD-50	Flight Controls - Rudder Control Cable Fitting - Inspection / Reinforcement
CF-2015-03	2015-03-16	BOMBARDIER	BD-700	Doors - Passenger Door External Handle Detent Seizure
2015-0047	2015-03-16	AIRBUS	A380	Airplane Flight Manual - Engine Interface Power Management Reset - Amendment