



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2015-07R1	2016-10-21	BOMBARDIER	DHC-8	Flight Control System - Cracking of the Spoiler Power Control Unit
2016-0209	2016-10-21	AIRBUS	A330, A340	Fuselage - Longitudinal Doubler at Vertical Tail Plane Attachment Cut Out - Inspection / Modification
US-2016-21-02	2016-10-20	SIKORSKY	S-92	Fire Protection - Fire Bottle Inertia Switch Wiring / Fire Extinguishing System - Modification / Test
2016-0050R1	2016-10-20	AIRBUS	A380	Engine Fuel & Control - Engine Interface Power Management - Reset
2016-0007R1	2016-10-20	AIRBUS	A380	Fuselage - Cabin and Cargo Compartment Structural Parts - Inspection / Replacement [Improper Heat Treatment]
US-2016-20-03	2016-10-20	BOEING	767	Fuselage - Outer Skin - Inspection
2016-0207	2016-10-19	AIRBUS	A330	Fuselage - Structural Parts / Joints - Modification / Reinforcement
2016-0208	2016-10-19	AIRBUS	A340	Fuselage - Structural Parts / Joints - Modification / Reinforcement
2016-0204	2016-10-19	AIRBUS	A319, A320, A321	[Correction] Electric and Electronic Common Installation - Battery Retaining Rod - Inspection
US-2016-21-04	2016-10-18	CONTINENTAL MOTORS, INC	TSIO-550, TSIOF-550	Engine Oil - Oil Cooler Cross Fitting Assembly - Replacement
US-2016-20-15	2016-10-17	GENERAL ELECTRIC	GEnx	Engine - Fan Stator Module Assembly - Rework
CF-2016-32R1	2016-10-14	BOMBARDIER	CL-600 (Challenger)	Fuel - Engine and Auxiliary Power Unit Electrical Fuel Pump Cartridge/Canister Fuel Leakage
2016-0206	2016-10-14	AIRBUS	A318, A319, A320, A321	[Correction] Fuselage - Pressure Panel Longitudinal Beams - Inspection / Repair / Modification
2014-0076R1	2016-10-14	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Fuselage - Rear Structure Junction Frame Reinforcement Angles - Inspection
US-2016-18-17	2016-10-14	HONEYWELL INTERNATIONAL INC.	TPE331, TSE331-3U	Engine - 2nd Stage Compressor Impeller - Removal
CF-2016-33	2016-10-13	VIKING AIR LTD	CL-215	Equipment - Loose Clamping of the Pilot and Co-pilot Portable Oxygen Bottle
2016-0205	2016-10-13	AIRBUS	A319, A320	Aircraft Flight Manual - Section Limitations / Fuel Gravity Feed Procedure - Amendment
US-2016-20-14	2016-10-13	BOEING	737	Fuselage - Window Corner Surround Structure - Inspection
2016-0201	2016-10-11	EADS CASA	CN-235	Fire Protection - Engine Fire Extinguisher Discharge Cartridge Wiring - Inspection / Modification
2016-0200	2016-10-11	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Equipment / Furnishings - External Life Raft Jettison System / Inflation Cylinder Percussion System / Bellcrank - Inspection
2016-0055R1	2016-10-11	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine - Accessory Gear Box Module M01 - Inspection / Replacement
2016-0203	2016-10-10	DIAMOND AIRCRAFT INDUSTRIES	DA 40	Turbocharging - V-band Clamps - Inspection / Replacement
2006-0139R1	2016-10-10	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Flight Controls - Lift Spoiler Actuators - Inspection