



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0220	2016-11-04	AIRBUS HELICOPTERS	AS 350 / EC 130	Rotor Flight Controls - Dual Hydraulic System - Modification
2016-0221	2016-11-04	ENSTROM HELICOPTER CORPORATION	280, 480, F-28	Main Rotor - Main Rotor Spindle - Inspection
US-2016-18-16	2016-11-03	BOEING	737	Centre/Auxiliary Tank Fuel Boost Pumps Installation - Modifications / P5-2 Fuel System Module Assembly - Replacement / AFM, Placard and Maintenance Program Changes
US-2016-22-11	2016-11-03	ENGINE ALLIANCE LLC	GP7200	High Pressure Turbine Stage 2 Nozzles - Inspection / Replacement
2016-0219	2016-11-03	AIRBUS	A340	Landing Gear - Nose Landing Gear Hydraulic Control Unit - Replacement
CF-2011-30R1	2016-11-03	BOMBARDIER	CL-600 (Regional Jet)	Fuselage - Cracking on the Forward Face of the Rear Pressure Bulkhead Web
2016-0217	2016-11-02	AIRBUS	A310	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Amendment
BR-2016-07-02	2016-11-02	EMBRAER	EMB-120	Time Limits / Maintenance Checks - Landing Gear Parts Life Limitations - Implementation
BR-2016-07-01	2016-11-02	EMBRAER	EMB-135, EMB-145	Flight Controls - Gust Lock Lever - Replacement
US-2016-22-05	2016-11-02	PRATT & WHITNEY	PW4100	Engine Fuel & Control - Fuel Nozzles - Initial and Repetitive Inspections / Replacement
US-2016-21-07	2016-11-02	HONEYWELL INTERNATIONAL INC.	TPE331	Engine Fuel & Control - Woodward Fuel Control Unit - Inspection / Update of Airplane Operating Procedures
2016-0218	2016-11-02	AIRBUS	A300-600	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Amendment
CF-2009-41R1	2016-11-02	BELL HELICOPTER TEXTRON CANADA (BHTC)	206	Fuselage - Cracking of Tail boom Fitting
2016-0216	2016-10-28	LEONARDO S.p.A. HELICOPTERS	AW189	Windows - Cockpit Doors and Cabin Emergency Exit Windows / Seals and Wedges - Replacement
2016-0109R1	2016-10-27	AIRBUS HELICOPTERS	AS 355	Fuel - FUELTRON Flowmeter - Removal
2016-0215	2016-10-27	ROLLS-ROYCE PLC	TRENT 1000	Engine - High Pressure Turbine Blades - Inspection / Replacement
2016-0214	2016-10-27	SLINGSBY	T67	Flight Controls - Brake Master Cylinder Pivot Pins - Inspection / Replacement
2016-0213	2016-10-26	LEONARDO S.p.A. HELICOPTERS	A109/A119	Main Rotor - Blades - Inspection
2016-0212	2016-10-25	AIRBUS	A318, A319, A320, A321	Fuselage - Central Vertical Strut at Frame 65 - Modification



Publ. number	Issue Date	TC Holder	Type	Subject
US-2016-19-03	2016-10-24	BOEING	747	Fuel - Wire Bundles inside the Forward and Aft Boost Pumps of the Main Fuel Tanks - Replacement
2016-0210	2016-10-24	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	B/E AEROSPACE FISCHER GmbH - Seat Energy Absorber Assembly - Replacement
2016-0211	2016-10-24	BAE SYSTEMS (OPERATIONS) LTD	ATP	Fuel - Cross Feed Fuel Pipe - Replacement