



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0029R1	2016-11-17	FOKKER SERVICES	F28	Fuselage - Upper Fuselage Skin External Doublers at TCAS Antenna Position - Inspection
2016-0229	2016-11-15	AIRBUS	A300, A300-600, A300-600ST (Beluga), A310	Wing - Damage Limitations Changes in Structural Repair Manual - Inspection / Repair
US-2016-22-18	2016-11-14	BOEING	MD-90	Fuselage - Cant Station 1520 Bulkhead - Inspection /Repair
2016-0228	2016-11-14	GROB AIRCRAFT AG	G 109	Landing Gear - Tail Wheel Mounting Bracket - Inspection / Repair
CF-2016-34	2016-11-11	BOMBARDIER	CL-600 (Challenger)	Fuselage - Improperly Installed Shims at the Wing Tie Beam Bumper Pads
2016-0227	2016-11-10	ROLLS-ROYCE PLC	RB211 TRENT 500	Engine - Low Pressure Fuel Tubes, Clips and Fuel Oil Heat Exchanger Mounts - Inspection
US-2016-20-02	2016-11-10	BOEING	737	Fuselage - Aft Pressure Bulkhead Web - Inspection
2016-0226	2016-11-10	AIRBUS	A340	[Correction] Aircraft Flight Manual / Engine Bleed Air System - Amendment
2016-0225	2016-11-09	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Wings - Rear Spar Root Joint Attachment Fittings at Wing Rib 2 - Inspection
2016-0224	2016-11-09	BAE SYSTEMS (OPERATIONS) LTD	HP 137 JETSTREAM MK 1, JETSTREAM200, JETSTREAM3100	Landing Gear - Main Landing Gear - Inspection / Replacement
2016-0223	2016-11-08	ROLLS-ROYCE PLC	RB211 TRENT 800	Engine - High Pressure Compressor Stage 1-4 Rotor Disc Shafts - Life Limit Reduction
2016-0222	2016-11-07	AIRBUS	A318, A319, A320	Wings - Bottom Panel 2 at Rib 2 Interface - Inspection
US-2016-19-12	2016-11-07	BOEING	747	Fuel - Wire Bundles of the Front Spars and Rear Spars of the Wings - Installation / Inspection
US-2016-22-09	2016-11-07	BOEING	757	Fuselage - Skin Lap Splice - Inspection