



Publ. number	Issue Date	TC Holder	Type	Subject
US-2017-06-11	2017-05-05	AIR COMM CORPORATION, AIRBUS HELICOPTERS	EASA STC 10016784, STC EASA.IM.R.S.01125, STC SR00491DE, EC 120 B	NOT ADOPTED - EASA DECISION ATTACHED
2017-0080	2017-05-05	AIRBUS HELICOPTERS	AS 350 / EC 130	Fuselage - Tail Boom / Fenestron Junction Frame - Inspection
2017-0075R1	2017-05-05	ROLLS-ROYCE PLC	RB211 TRENT 900	Powerplant - Drains Mast - Inspection / Replacement
2017-0077	2017-05-03	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Rotorcraft Flight Manual / Emergency Procedures - Amendment
2017-0078	2017-05-03	AIRBUS	A330	Stabilizers - Horizontal Stabilizer / Center Box Top Skin - Inspection / Repair
2017-0076	2017-05-03	AIRBUS	A380	Time Limits / Maintenance Checks - System Equipment Maintenance Requirements - ALS Part 4 - Amendment
CF-2017-14	2017-05-02	BOMBARDIER	CL-600 (Regional Jet)	Landing Gear - Failure of Main Landing Gear Shimmy Damper Belleville Washers
US-2017-08-08	2017-04-28	CFE COMPANY	CFE738	Engine - High-Pressure Compressor (HPC) Impeller - Removal / Replacement
2017-0074	2017-04-28	DIAMOND AIRCRAFT INDUSTRIES	DA 42 / 62	Flight Controls - Flap Control System / Bell Crank Assembly - Inspection / Modification
2015-0234-CN	2017-04-28	AIRBUS	A319, A320, A321	CANCELLED: Doors - Main Landing Gear Door Tie Rod Assembly - Inspection
2017-0073	2017-04-27	BAE SYSTEMS (OPERATIONS) LTD	JETSTREAM3100, JETSTREAM3200	Time Limits / Maintenance Checks - Corrosion Prevention and Control Programme - Amendment
2017-0071	2017-04-26	ROLLS-ROYCE PLC	RB211 TRENT 700	Engine - Compressor Intermediate Case - Inspection / Repair
2017-0072-E	2017-04-26	STEMME AG	S10, S12	Propeller - Gearbox - Replacement / Modification



Publ. number	Issue Date	TC Holder	Type	Subject
2013-0306-CN	2017-04-26	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	CANCELLED: Fuel - Fuel System / Supply Tank Indication - Check
2006-0318R2	2017-04-25	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Rotorcraft Flight Control - Tail Rotor Control Linear Transducer (LVDT Collective) Bearing - Inspection/Replacement and Rod and Floor Modification
2017-0069	2017-04-25	AIRBUS	A330, A340	Wings - Centre Wing Box Fastener Holes at Frame 40 Vertical Web - Inspection / Modification
US-2017-05-51	2017-04-25	AIR COMM CORPORATION, BELL HELICOPTER TEXTRON CANADA (BHTC)	EASA STC 10028717, STC SR00693DE, 429	[Final Rule] Air Conditioning - Condenser Blower-to-Motor Attachment - Inspection / Deactivation
2017-0070	2017-04-25	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Pipe Injector Preferred Assembly - Replacement
CF-2016-01R2	2017-04-25	BELL HELICOPTER TEXTRON CANADA (BHTC)	429	Tail Rotor - Pitch Link Corrosion
2017-0067	2017-04-24	SAAB AB, AERONAUTICS	340	Flight Controls - Stall Warning and Identification System / Stall Warning Computer - Modification / Replacement
2017-0068	2017-04-24	FOKKER SERVICES	F28	Landing Gear - Landing Gear Handle Teleflex Mechanism - Inspection / Lubrication
BR-2017-04-01	2017-04-24	EMBRAER	ERJ-190	Nacelles / Pylons - Pylon Lower Link Fittings - Modification