



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0092-E	2017-05-19	DUC, SOCIETE	FLAIR-2	Propellers - Removal from Service
2017-0091	2017-05-19	AIRBUS	A318, A319, A320, A321, A330, A340	Navigation - Traffic Collision Avoidance System Processor - Modification (Software Update) / Replacement
CF-2017-17	2017-05-19	VIKING AIR LTD	DHC-2	Wing - Cracking of Flap and Aileron hinge arm support brackets and Rear Spar Web
CF-2016-36R1	2017-05-17	BOMBARDIER	DHC-8	Landing Gear - Main Landing Gear Retraction Actuator Rod-End Failure
CF-2017-15	2017-05-17	BOMBARDIER	DHC-8	Landing Gear - Main Landing Gear Up-Lock Assembly Latch Wear - Introduction of One-Star Certification Maintenance Requirement Task 323100-102
2017-0089	2017-05-17	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Main Rotor - MR Mast Upper Bearing Lubrication / MR Mast Jet Oil Hose - Inspection
US-2017-08-01	2017-05-17	GULFSTREAM AEROSPACE CORPORATION	GV	Fuel - Fuel Boost Pump - Inspection / Replacement - Airplane Maintenance Program - Revision
2017-0090	2017-05-17	DIAMOND AIRCRAFT INDUSTRIES	DA 42 / 62	Engine Exhaust - Exhaust Pipes - Modification / Inspection
2017-0088	2017-05-16	ROLLS-ROYCE PLC	TRENT XWB	Engine - Intermediate Pressure Turbine Stage 2 Locking Plates - Inspection
CF-2017-07R1	2017-05-16	BOMBARDIER	CL-600 (Challenger)	Cold Weather Operations - Introduction of Low Temperature Ground Wing Anti-Ice System
2016-0036-CN	2017-05-15	ROLLS-ROYCE PLC	TRENT XWB	CANCELLED: Engine - Low Pressure Compressor / Shaft Attachment - Inspection
US-2017-08-07	2017-05-15	LEARJET, INC.	60	Fuselage - Fuselage Skin - Inspection
US-2017-07-06	2017-05-15	GULFSTREAM AEROSPACE CORPORATION	G-1159	Flight Controls - Rudder Assembly - Inspection / Replacement - Modification
2017-0087	2017-05-12	LEONARDO S.p.A. HELICOPTERS	AW189	Main Rotor - Main Rotor Slip Ring - Inspection / Replacement
2017-0086	2017-05-12	DIAMOND AIRCRAFT INDUSTRIES	DA 40	Engine Controls - Electronic Control Unit - Modification
2017-0084	2017-05-12	CFM INTERNATIONAL	CFM56-5, CFM56-5B	Engine - Radial Drive Shaft - Replacement
2017-0085-E	2017-05-12	LEONARDO S.p.A. HELICOPTERS	A109/A119	Stabilizers - Elevator Assembly - Inspections
US-2017-07-09	2017-05-10	SIKORSKY	S-92	Tail Rotor Drive - Tail Gearbox Center Housing - Removal from Service (Retirement Life)
2017-0083	2017-05-10	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Main Rotor - Main Rotor Slip Ring - Inspection / Replacement
US-2017-09-06	2017-05-08	GENERAL ELECTRIC	GEnx	Engine Controls - Full Authority Digital Engine Control (FADEC) Software



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0081	2017-05-08	AIRBUS	A310	Wing - Wing Top Skin Panel Attachments at Rib 2 and Rib 3 - Inspection / Repair / Modification
2017-0082	2017-05-08	AIRBUS	A300, A300-600, A310	Fuselage - Bulk Cargo Door - Inspection / Repair
2007-0242R1	2017-05-08	AIRBUS	A310	Wings - Outer Wings Structural Fatigue - Inspection/Modification