



Publ. number	Issue Date	TC Holder	Type	Subject
2008-0165R1	2017-06-30	AIRBUS HELICOPTERS	SA 365/366 / AS 365 / EC 155	Rotor(s) - Starflex Star Arm Ends - Check / Replacement
US-2017-11-14	2017-06-29	BOEING	777	Wings - Fuel Tank Boundary Structure Wire Bundle Clamp Teflon Sleeves - Installation / Inspection
CF-2017-21R1	2017-06-29	BOMBARDIER	DHC-8	Engine Ignition - Loss of #2 Engine Auto Relight Function
2017-0113	2017-06-28	FOKKER SERVICES	F28	Equipment / Furnishing - Passenger Service Unit and Overwing Emergency Exit Door - Inspection / Modification
2017-0114	2017-06-28	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Stabilizers - Vertical Fin - Inspection
2017-0064R1	2017-06-27	SAFRAN HELICOPTER ENGINES	ARRIEL 1	Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement
US-2017-12-07	2017-06-27	BOEING	737	Air Conditioning - Temperature Control Valve / Control Cabin Trim Air Modulating Valve - Replacement
US-2017-13-01	2017-06-27	BOEING	737	Fuselage - Frame Inboard Chords - Inspection
CF-2015-13R1	2017-06-27	BOMBARDIER	DHC-8	Stabilizers - Cracked Barrel Nut at the Horizontal Stabilizer to Vertical Stabilizer Attachment Joint
US-2017-12-05	2017-06-27	BOEING	737	Fuselage - Station 259.5 Circumferential Butt Splice - Inspection
2017-0112	2017-06-26	LEONARDO S.p.A. HELICOPTERS	AW169	Rotorcraft Flight Manual / Limitations Section - Amendment
2017-0109	2017-06-23	AIRBUS HELICOPTERS	AS 350 / EC 130	[Correction] Electrical Power - Starter Generator and Brushes - Inspection / Replacement
2017-0110	2017-06-23	LEONARDO S.p.A. HELICOPTERS	AW169	Landing Gear - Retraction Actuators - Installation / Replacement
2017-0111	2017-06-23	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gearbox Particle Detector / Oil Filter / Oil Cooler - Inspection Main Rotor Drive - Epicyclic Module - Replacement / Modification / Reduced Service Life Limit
2017-0107	2017-06-22	SCHEIBE	SF25	Exhaust - Exhaust Duct / End-pipe - Inspection / Modification
2017-0108	2017-06-22	DASSAULT AVIATION	Falcon 10	Ice and Rain Protection - Wing Anti-Ice Hose - Replacement
US-2017-12-14	2017-06-21	BOEING	757	Fuselage - Frame Webs - Inspection / Modification



Publ. number	Issue Date	TC Holder	Type	Subject
US-2017-12-12	2017-06-21	BOEING	757	Fuselage - Circumferential Splice Plates - Repetitive Inspections
US-2017-12-01	2017-06-20	BOEING, BOEING - WICHITA DIVISION	767, STC ST01329WI-D	NOT ADOPTED - EASA DECISION ATTACHED
2017-0106	2017-06-19	DASSAULT AVIATION	Falcon 2000, Falcon 900EX, Mystère-Falcon 900	Wings - Slat Extension Mechanical Stop Assembly - Inspection
CF-2014-45R3	2017-06-19	BOMBARDIER	DHC-8	Nacelle - A-Frame Structure - Insufficient Fillet Radius and Fouling with Main Landing Gear Stabilizer Brace and the Electrical Wiring Harnesses
CF-2011-30R2	2017-06-19	BOMBARDIER	CL-600 (Regional Jet)	Fuselage - Cracking on the Forward Face of the Rear Pressure Bulkhead Web