



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0146	2017-08-10	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Rotorcraft Flight Manual - Limitations Section - Amendment
2017-0147	2017-08-10	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Rotors Flight Control - Tail Rotor Controls - Modification
US-2017-14-03	2017-08-10	SIKORSKY	S-92	Landing Gear - Components - Life Limit / Inspection
2017-0144	2017-08-09	SAAB AB, AERONAUTICS	340	Ice and Rain Protection - Horizontal Stabilizer De-icing Boots - Inspection / Replacement; Aircraft Flight Manual - Amendment
2017-0143	2017-08-08	AIRBUS HELICOPTERS	AS 350 / EC 130	Electrical Power - Direct Current (Optional) Second Battery - Replacement
2017-0141	2017-08-08	AIRBUS	A380	Fuselage - Landing Gear Bay / Frame 59 - Tension Bolts / Nuts - Inspection / Replacement
2017-0142	2017-08-08	DASSAULT AVIATION	Fan Jet Falcon, Mystère-Falcon 20, Mystère-Falcon 20GF/200, Mystère-Falcon 50	Doors - Main Entrance Door Placard - Installation / Replacement
2017-0139	2017-08-04	LEONARDO S.p.A. HELICOPTERS	AW189	Fuselage - Underbelly Tank Fuel Sump Electrical Bonding - Modification
CF-2015-15R1	2017-08-03	BELL HELICOPTER TEXTRON CANADA (BHTC)	429	Time Limits & Maintenance Checks - Life-Limited Pylon Restraint Spring Assembly Rod End Not Serialized
2017-0138	2017-08-02	AIRBUS	A318, A319, A320, A321	Powerplant - Aft Engine Mounts Retainers - Inspection / Replacement
CF-2015-28R1	2017-08-02	BOMBARDIER	CL-600 (Regional Jet)	Equipment / Furnishings - Damaged Decompression Window Louver Panel Assemblies and Detached Blowout Panels
CF-2017-27	2017-08-02	BOMBARDIER	CL-600 (Regional Jet)	Wings - Cracking of the Main Landing Gear Trunnion Fitting Assembly
2017-0137	2017-08-01	LEONARDO S.p.A. HELICOPTERS	AW169	Rotors Flight Control - Collective Fixed Friction Force - Check
US-2017-13-11	2017-08-01	GULFSTREAM AEROSPACE CORPORATION	GIV	Flight Controls - Gust Lock System - Modification / Maintenance or Inspection Program Revision
US-2017-15-02	2017-08-01	BELL HELICOPTER TEXTRON Inc. (BHTI)	212, 412	Engine Oil - Fuel Check Valve - Replacement
CF-2017-25	2017-08-01	BOMBARDIER	DHC-8	Windows - Windshield Cracking
CF-2017-26	2017-08-01	BOMBARDIER	BD-100	Auxiliary Power Unit (APU) Inlet Fire during In-flight APU Start



Publ. number	Issue Date	TC Holder	Type	Subject
US-2017-10-10	2017-07-31	SIKORSKY	S-92	Fire Protection - Engine Flame Detector Bracket Assembly and Harness Assembly - Installation
2017-0136	2017-07-31	SCHLEICHER, ALEXANDER	ASH 25, ASH 26, ASK 21, ASW 22	Exhaust - Silencer - Replacement