



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0158	2017-08-25	AIRBUS	A300-600, A300-600ST (Beluga)	Wings - Fuselage Frame 40 Lower Outboard Radius - Inspection
2017-0159	2017-08-25	AIRBUS HELICOPTERS	AS 355	Tail Rotor Drive - Fan Assembly - Inspection
2017-0157	2017-08-25	BAE SYSTEMS (OPERATIONS) LTD	JETSTREAM3100, JETSTREAM3200	Time Limits / Maintenance Checks - Airworthiness Limitations / Main and Nose Landing Gears - Amendment
US-2017-17-04	2017-08-24	BOEING	737	Wings - Upper Aft Skin of the Wings - Repetitive Inspections
2017-0156	2017-08-24	LEONARDO S.p.A. HELICOPTERS	AW169	Auto Flight - Automatic Flight Control System - Software Update Rotorcraft Flight Manual / Limitations Section - Amendment
2017-0155	2017-08-23	LEONARDO S.p.A. HELICOPTERS	AW169	Windows - Emergency Exit Window Seal, Non-Metallic Channel and Handle - Replacement
US-2017-14-06	2017-08-22	SIKORSKY	269	Main Rotor Drive - Tachometer Markings & Driveshaft - Installation / Inspection
2017-0154-E	2017-08-22	AIRBUS	A350	Hydraulic System / Fuel Tank Inerting System - Engine Driven Pump Rapid Overheat - Master Minimum Equipment List Restriction
2017-0151	2017-08-18	GE AVIATION CZECH	H75, H80, H85, M601	Engine - Exhaust System - Modification
2017-0153	2017-08-17	AIRBUS	A300, A300-600, A300-600ST (Beluga), A310	Landing Gear - Parking Brake Operated Valve - Replacement
2017-0152	2017-08-17	AIRBUS	A330, A340	Fuel - Trim Tank Overflow - Functional Test
2017-0149	2017-08-16	CFM INTERNATIONAL	CFM56-3	Engine - Variable Stator Vane Actuating System - Check
2017-0150	2017-08-16	AIRBUS	A318, A319, A320, A321	Oxygen - Crew Oxygen / Oxygen Pipe Corrosion - Inspection
US-2017-14-10	2017-08-15	BOEING	MD-11	Fuel - Fuel Shroud - Check / Inspection / Test
US-2017-15-01	2017-08-15	BOEING	777	Auto Flight - Mode Control Panel (MCP) - Replacement
US-2017-16-11	2017-08-15	LYCOMING ENGINES	AEIO-320, AEIO-360, AEIO-390, AEIO-540, AEIO-580, AIO-320, GO-435, GO-480, GSO-480, HIO-360, HIO-540, HO-360, IGO-540, IGSO-540, IO-320, IO-360, IO-390, IO-540, IO-580, IO-720, IVO-360, LIO-320, LIO-360, LO-360, LTIO-540, LTO-360, O-145, O-235, O-290, O-320, O-340, O-360, O-435, O-540, TIGO-541, TIO-360, TIO-540, TIO-541, TO-360, VO-435, VO-540	Engine - Connecting Rods - Inspection / Replacement
2017-0148	2017-08-15	ROLLS-ROYCE PLC	VIPER MK 500, VIPER MK 601-22	Time Limits / Maintenance Checks - Engine Critical Parts Cyclic Life Limits - Amendment
US-2017-15-12	2017-08-14	BOEING	737	Fuselage - Skin Lap Splice at the Lower Fastener Row - Repetitive Inspections



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0140R1	2017-08-14	AIRBUS	A380	Fuselage - Cross Beam Fittings - Modification