



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0197	2017-10-06	ROLLS-ROYCE PLC	VIPER MK 601-22	Engine - Oil Pump Assembly / Oil Pressure Filter - Inspection / Replacement
US-2017-20-06	2017-10-06	HONEYWELL INTERNATIONAL INC.	AS907	Engine - Second Stage Low-Pressure Turbine (LPT2) Blade - Inspection
2017-0196	2017-10-05	AEROCONSEIL, AIRBUS, BRITISH AIRWAYS plc, FOKKER SERVICES, H4 AEROSPACE (UK) LTD, PMV ENGINEERING, SCANDINAVIAN AVIONICS DESIGN ApS	EASA STC 10045396, A318, A319, A320, A321, A330, A340, EASA STC 10039421, EASA STC 10047494, EASA STC 10051008, EASA STC 10047157, EASA STC 10047744, EASA STC 10050434, EASA STC 10050942, EASA STC 10051659, EASA STC 10051519, EASA STC 10054797	Navigation - Traffic Collision Avoidance System Processor - Modification (Software Update) / Replacement
2017-0195	2017-10-04	AIRBUS	A340	Exhaust - Thrust Reverser Outer Fixed Structure - Inspection / Replacement
2016-0166-E	2017-10-04	LEONARDO S.p.A. HELICOPTERS	AB204/AB205, AB212/AB412	[Correction] Main Rotor Drive - Spiral Bevel Gear - Inspection
US-2017-20-05	2017-10-04	BOEING	757	Fuselage - Crown Skin Panel - Inspection / Repair / Replacement
US-2017-19-02	2017-10-02	BOEING	727	Doors - Main Cargo Door Cam Support Assemblies - Inspection
US-2017-17-19	2017-09-29	BOEING	DC-9, MD-88	Fuselage - Bulkhead Structures - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
US-2017-20-01	2017-09-29	HONEYWELL INTERNATIONAL INC.	TFE731-20/-40/-50/-60	Turbine Engine Compressor Section - Fan Disks - Removal / Replacement
CF-2017-33	2017-09-29	VIKING AIR LTD	DHC-2	Airframe - Corrosion
2017-0193	2017-09-29	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Main Rotor Drive - Main Rotor Mast - Inspection
US-2017-17-18	2017-09-29	GENERAL ELECTRIC	CF34-8	Turbine Engine - Fan Blades - Life Limit Reduction
2017-0194-E	2017-09-29	AIRBUS HELICOPTERS	EC175	Stabilizers - Horizontal Stabilizer Attachment Bolts - Inspection / Modification / Clearance Check Rotorcraft Flight Manual - Amendment
2017-0192	2017-09-28	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	RECARO Aircraft Seating GmbH & Co. KG - Passenger Seats - Modification
CF-2017-32	2017-09-28	BOMBARDIER	BD-700	Flight Controls - Elevator Control System Bracket Cracking
US-2017-19-20	2017-09-26	GENERAL ELECTRIC	CT7-8, CT7-9	Turbine Engine - High-Pressure Compressor Impeller - Removal
US-2017-19-10	2017-09-26	BOEING	757	Doors - Main Cargo Door Cam Support Assemblies - Inspection / Replacement
CF-2017-31	2017-09-25	BOMBARDIER	BD-700	Fuselage - Attachments for Belly Fairing Access Panels - Replacement
2017-0190	2017-09-25	AIRBUS HELICOPTERS	EC175	Fuel System - Additional Fuel Tank 4 - Inspection
2017-0191-E	2017-09-25	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Main Rotor - Rotating Swashplate Yokes - Inspection / Rework