



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|---------------------------------------|--|--|
| CF-2018-18 | 2018-07-13 | BELL HELICOPTER TEXTRON CANADA (BHTC) | 429 | Tail Rotor Drive - Loose Tail Rotor Gearbox |
| 2018-0145R1 | 2018-07-13 | AIRBUS | A350 | Flight Controls - Elevators and Rudder Servocontrols - Replacement |
| 2018-0147 | 2018-07-13 | AIRBUS | A330 | Fuselage - Cabin and Cargo Compartments Structural Parts - Inspection / Replacement |
| 2018-0148 | 2018-07-13 | AIRBUS | A330 | Exhaust - Thrust Reverser Lower Beam - Inspection / Repair |
| 2018-0149-E | 2018-07-13 | LEONARDO S.p.A. HELICOPTERS | A109/A119 | Electrical Power - Electrical Cables - Inspection / Modification |
| 2018-0146 | 2018-07-12 | AIRBUS | A330 | Fuselage - Frame 40 Skin Panel Junction - Inspection |
| US-2018-14-01 | 2018-07-11 | PIPER AIRCRAFT INC. | PA-46 (Malibu) | AFM Change / Placard Installation - Cockpit Area Fuselage Skin - Inspection / Repair |
| CF-2018-17 | 2018-07-09 | BOMBARDIER | CL-600 (Regional Jet) | Stall Protection System - Out of Tolerance Angle of Attack Transducers |
| US-2018-11-13 | 2018-07-09 | BOEING | 787 | Wings - Upper Wing Stringers - Inspection / Maintenance Program Revision |
| US-2018-13-05 | 2018-07-09 | HONEYWELL INTERNATIONAL INC. | TPE331, TSE331-3U | Engine - Oil Filter Sampling / Analysis - Hydraulic Torque Sensor Gear Assembly - Inspection |
| US-2018-12-06 | 2018-07-09 | BOEING | 787 | Air Conditioning - Software and Hardware - Installation |
| 2018-0135R1 | 2018-07-06 | AIRBUS | A318, A319, A320, A321 | Landing Gear - Main Landing Gear Sliding Tube - Inspection / Replacement |
| 2018-0144 | 2018-07-06 | AIRBUS, AIRBUS S.A.S. | A330, A340, EASA STC 10062892, EASA STC 10064120 | Fuselage - Emergency Locator Transmitter Antenna - Inspection |
| 2018-0128R1 | 2018-07-06 | ROLLS-ROYCE PLC | TRENT 1000 | Engine - Intermediate Pressure Compressor Blades / Shafts - Inspection |
| 2018-0143-E | 2018-07-06 | Glasfaser-Flugzeug-Service GmbH | BS 1, Club Libelle 205, Glasfluegel 304, Glasfluegel 604, H301, Hornet, Hornet C, KESTREL, Mosquito, Mosquito B, Standard Libelle, Standard Libelle 201B, Standard Libelle 203 | Equipment / Furnishings - Towing Release Mechanism - Inspection |
| 2018-0142-E | 2018-07-04 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225 | Equipment & Furnishings / Ice and Rain Protection / Fuselage - Removal |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|--------------|------------|-----------|------|---|
| 2018-0141 | 2018-07-03 | AIRBUS | A350 | Flight Controls - Aileron, Elevator and Rudder Electro-Hydrostatic Actuators - Inspection / Replacement |