



Publ. number	Issue Date	TC Holder	Type	Subject
2018-0179	2018-08-23	AIRBUS	A350	Time Limits / Maintenance Checks - Certification Maintenance Requirements - ALS Part 3 - Amendment
2018-0178	2018-08-23	AIRBUS	A350	Hydraulic System / Fuel Tank Inerting System - Engine Driven Pump Rapid Overheat - Master Minimum Equipment List Restriction / Software Update / Modification
US-2018-17-03	2018-08-22	BOEING	787	Ice and Rain Protection - Cabin Air Compressor Inlet Ice Protection System Wiring - Modification
2018-0177	2018-08-21	AIRBUS HELICOPTERS	EC175	Rotor Drive - Main Gearbox Magnetic Plugs - Inspection
US-2018-17-04	2018-08-21	ROLLS-ROYCE CORPORATION (USA)	AE 2100, AE 3007	Engine - Turbine Wheels - Removal / Replacement
2018-0176	2018-08-21	AIRBUS HELICOPTERS	SA 365/366 / AS 365 / EC 155	Main Rotor Drive - Main Gearbox Magnetic Plug - Replacement
US-2018-13-06	2018-08-15	BOEING	767	Wings - Lower Outboard Wing Skin - Inspection
2018-0175-E	2018-08-15	LEONARDO S.p.A. HELICOPTERS	AB206	Engine - Power Turbine Limitations - Operational Limitation
US-2018-14-06	2018-08-15	AMERICAN CHAMPION AIRCRAFT CORP	8 series	Wings - Aileron Hinge Support - Inspection / Installation
CF-2018-22	2018-08-15	BOMBARDIER	BD-700	Electrical Power - Variable Frequency Generator Harness Low Clearance to Hydraulic/Fuel Lines
2018-0174	2018-08-14	AIRBUS	A310	Wings - Top Skin Stringer Joints at Rib 19 - Inspection / Modification