



Publ. number	Issue Date	TC Holder	Type	Subject
2019-0121	2019-05-29	LEONARDO S.p.A. HELICOPTERS	AW169, AW189	Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check
2019-0120	2019-05-29	FOKKER SERVICES	F28	Electrical Power - Power Transfer Contactors - Replacement
2019-0117	2019-05-29	MECAER AVIATION GROUP SpA	AMD-500N, NH-500D	Main Rotor - Blades - Inspection / Replacement
2019-0118	2019-05-29	AIRBUS HELICOPTERS	EC175	Equipment / Furnishings - Emergency Flotation Unit - Replacement Rotorcraft Flight Manual / Master Minimum Equipment List - Revision
2019-0119-E	2019-05-29	LEONARDO S.p.A. AIRCRAFT	F260	Flight Controls - Flap Actuator - Inspection / Replacement
2019-0115	2019-05-28	AIRBUS	A350	Equipment / Furnishings - Baby Bassinet Inserts - Inspection / Modification
2019-0114	2019-05-24	AIRBUS	A340	Wings - Lower Skin Covers at Rib Bay 3/4 - Inspection
2019-0113	2019-05-24	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine Fuel & Control - Engine Electronic Control Software - Update
CF-2016-32R3	2019-05-23	BOMBARDIER	CL-600 (Challenger)	Fuel - Engine and Auxiliary Power Unit Electrical Fuel Pump Cartridge/Canister Fuel Leakage
CF-2018-26R1	2019-05-23	BOMBARDIER	CL-600 (Challenger)	Landing Gear - Main Landing Gear Side Stay Actuators Contain Non-Conforming Split Ball Bearing
BR-2019-05-01	2019-05-22	EMBRAER	ERJ-170	Time Limits / Maintenance Checks - Airworthiness Limitation Section / Maintenance Program - Revision
CF-2019-21	2019-05-22	BOMBARDIER	CL-600 (Regional Jet)	Wing Structure - Lower Wing Plank - Cracking at Stringer Run-out
2017-0020R1	2019-05-22	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Tail Rotor - Pitch Rod - Inspection
BR-2019-05-02	2019-05-22	EMBRAER	ERJ-190	Time Limits / Maintenance Checks - Airworthiness Limitation Section / Maintenance Program - Revision
2019-0112	2019-05-21	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT XWB	Engine Fuel & Control - Engine Electronic Controller Software - Update
2019-0111	2019-05-21	ATR	ATR42, ATR72	Oxygen - Crew and Passenger Oxygen Cylinders - Inspection / Replacement
2019-0110	2019-05-21	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine - Torque Conformation Box - Check
2019-0109	2019-05-20	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Tail Rotor - Rotor Blades - Inspection / Modification
CF-2019-18	2019-05-20	BOMBARDIER	BD-700	Oxygen System - Insufficient Accessibility to the Portable Oxygen Bottle