



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2019-33	2019-09-20	BOMBARDIER	BD-700	Landing Gear - Trailing Arm Assembly Axle Bore Corrosion
2019-0230	2019-09-20	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	[Correction] Engine - Oil Service Pipe Sealing Rings - Inspection / Replacement / Modification / Rework
2019-0235	2019-09-20	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Inspection / Modification / Replacement
2019-0237-E	2019-09-20	DG-FLUGZEUGBAU	DG-1000, DG-500	Cabin Systems - Canopy Lock / Rear Locking Rods - Inspection / Check / Repair Aircraft Flight Manual - Amendment
2019-0234	2019-09-19	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT XWB	Engine - Front Engine Mount Support Structure - Inspection
2012-0108R1	2019-09-19	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Fuselage - Frame No.9 - Inspection / Repair
2019-0233	2019-09-19	AIRBUS	A319, A320, A321	[Correction] Wings - Overwing Panel - Inspection
2019-0229R1	2019-09-18	AIRBUS	A380	Exhaust - Thrust Reverser Cascades and Aft Frame Attachment - Inspection / Modification
2018-0234R2	2019-09-17	AIRBUS	A350	Exhaust - Thrust Reverser Actuators - Greasing / Master Minimum Equipment List Restriction - Amendment
US-2019-18-01	2019-09-17	INTERNATIONAL AERO ENGINES AG	V2500-( )5	Turbine - Low-Pressure Turbine Stage 6 Disks - Replacement
2019-0232	2019-09-16	AIRBUS	A319, A320, A321	Hydraulic Power - Hydraulic Reservoir Pressurisation Lines - Modification
2012-0130-CN	2019-09-13	AEROPHILE S.A.	5500	CANCELLED: Standard Practices and Structure - Envelope Rip Panel - Inspection
2019-0231	2019-09-13	PILATUS AIRCRAFT LTD	PC-12	Flight Controls - Flap Drive System / Flap Fairings and Front Inboard Tension Rods - Inspection / Modification / Replacement
CF-2016-13R1	2019-09-13	BELL HELICOPTER TEXTRON CANADA (BHTC)	206, 407	Main Rotor Drive - Loss of Lubrication to the Freewheel Assembly
US-2019-15-07	2019-09-13	BOEING	737	[Correction] Fuselage - Fuselage Lower Lobe Frames - Inspection
US-2019-10-51	2019-09-12	AIR METHODS CORPORATION, AIRBUS HELICOPTERS DEUTSCHLAND	FAA STC SR00592DE, MBB-BK 117	Fuselage - Fuselage Frame - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
US-2019-16-16	2019-09-12	AEROMETALS, INC., AEROSPACE FILTRATION SYSTEMS, INC, AIRBUS HELICOPTERS	EASA STC 10040685, FAA STC SR00811SE, STC EASA.IM.R.S.00273, EASA STC 10017072, STC EASA.IM.R.S.01509, STC SR02393CH, AS 350 / EC 130	Engine Air Intake System - Rotorcraft Flight Manual Supplement - Revision
2019-0228	2019-09-12	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Equipment / Furnishings - Electric Hoist Installation - Modification
CF-2019-14R1	2019-09-12	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
2019-0219	2019-09-11	AIRBUS, AIRBUS DEFENCE & SPACE S.A.	A330, EASA STC 10034690	Fuselage - Fuselage Bulk Cargo Door Frames - Inspection / Repair
2019-0226	2019-09-11	AIRBUS	A340	Landing Gear - Centre Landing Gear Wheel Axle - Replacement
2019-0227	2019-09-11	AIRBUS	A319, A320	Electric and Electronic Common Installation - Electrical Wiring - Modification
2019-0067R1	2019-09-11	AIRBUS	A318, A319, A320, A321	Fuselage - Lateral Cockpit Window Frame Upper Stiffener - Inspection
2019-0225-E	2019-09-11	AIRBUS HELICOPTERS	AS 350 / EC 130	Main Rotor Drive - Main Gearbox Drive Shaft / Engine Coupling - Inspection
CF-2019-31	2019-09-09	AIRBUS CANADA LP	BD-500 (A220 Series)	Ice and Rain Protection - Insufficient Engine Core Ventilation Resulting in Higher Engine Core Temperatures