



Publ. number	Issue Date	TC Holder	Type	Subject
US-2019-24-17	2019-12-23	BOEING	MD-90	Wings - Fastener Holes / Lower Skin - Inspection
US-2019-23-11	2019-12-23	GULFSTREAM AEROSPACE CORPORATION	GVI	Flight Controls - Airplane Flight Manual - Revision
2019-0316	2019-12-23	AIRBUS	A318, A319, A320, A321	Equipment / Furnishings - Emergency Escape Slide / Raft Inflation Reservoir - Pressure Check
2019-0315	2019-12-23	AIRBUS	A330	Fuselage - Frame 67 Stringer 44 Right Hand - Inspection
2019-0313	2019-12-20	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Rotors Flight Control - Tail Rotor Actuator - Inspection
2019-0314	2019-12-20	AIRBUS	A330, A340	Hydraulic Power - Ground Service Manifold Manual Valve Attachment Bolts - Replacement
2019-0310	2019-12-20	AIRBUS	A380	Flight Controls - Rudder Electrical Backup Hydraulic Actuator Solenoid Valves - Replacement / Master Minimum Equipment List - Amendment
2019-0312	2019-12-20	AIRBUS	A330, A340	Aircraft Flight Manual - Amendment
2019-0064R1	2019-12-19	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection / Modification
2019-0304R1	2019-12-19	AIRBUS	A320, A321	Engine - Operational Restrictions
2019-0309	2019-12-19	AIRBUS	A318, A319, A320, A321	Aircraft Flight Manual - Amendment
2019-0311	2019-12-19	LEONARDO S.p.A. HELICOPTERS	AB139/AW139, AB212/AB412	Equipment / Furnishings, Emergency Flotation System - Inflation Hoses - Inspection
US-2019-23-14	2019-12-18	BOEING	737	Fuel - Maintenance or Inspection Program - Revision
2019-0306	2019-12-18	DAHER AEROSPACE	TBM 700	Air Conditioning - Dump Switch - Modification
2019-0307	2019-12-18	RUAG AEROSPACE SERVICES, GMBH	228	Landing Gear - Carbon Brake Assembly - Inspection / Replacement
2019-0239R1	2019-12-18	XTREMEAIR GmbH	XA41, XA42	Power Plant - Engine Mount - Inspection / Placards & Markings - Aerobatics Manoeuvres Prohibited - Installation / Aircraft Flight Manual - Section Limitations - Amendment
CF-2019-30R1	2019-12-18	PRATT & WHITNEY CANADA	PT6A-100, PT6A-30	Compressor Turbine Blade Fracture due to Non-conforming CT Vane Installation
2019-0308	2019-12-18	AIRCRAFT INDUSTRIES	L 410/420 (Turbolet)	Landing Gear - Nose Landing Gear Leg / Pin - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2019-0305	2019-12-17	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Wiring Harness - Cabin Wiring Harness - Inspection
2019-0220R1	2019-12-17	AIRBUS	A380	Fuselage - Rear Cone Frame Feet 102/103 - Modification
US-2019-22-01	2019-12-17	BOEING	787	Wings - Side of Body Rib - Inspection
US-2019-22-02	2019-12-16	BOEING	747	Equipment / Furnishings - Captain's and First Officer's Seats - Inspection / Check
US-2019-22-05	2019-12-16	GENERAL ELECTRIC	CF34-8	Air - Operability Bleed Valve - Inspection
US-2019-25-01	2019-12-16	INTERNATIONAL AERO ENGINES LLC	PW1100 / PW1400	NOT ADOPTED - EASA DECISION ATTACHED
US-2019-23-06	2019-12-16	AVIATION PARTNERS BOEING, BOEING, VT MOBILE AEROSPACE ENGINEERING	EASA STC 10015659, FAA STC ST01518SE, STC EASA.IM.A.S.01636, 757, FAA STC ST03562AT	Fuselage - Fuselage Frame Web - Inspection
2019-0303	2019-12-16	AIRBUS HELICOPTERS	EC175	Landing Gear - Main Landing Gear - Inspection / Replacement