



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|---|--|--|
| 2020-0022 | 2020-02-07 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225 | Time Limits / Maintenance Checks - Main Gear Box / Particle Detectors - Inspection Main Rotor Drive - Planet Gear Assemblies - Replacement / Modification |
| 2020-0020-E | 2020-02-06 | AIRBUS | A350 | [Correction] Airplane Flight Manual - Abnormal / Normal Procedures Sections - Amendment |
| 2020-0021 | 2020-02-06 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225 | Tail Rotor - Tail Rotor Hub Pitch Control Rod - Inspection / Replacement |
| 2019-0279R1 | 2020-02-05 | AIRBUS | A320 | Fire Protection - Cargo Compartment Fire Extinguishing Pipes - Inspection / Modification |
| 2020-0019 | 2020-02-05 | AIRBUS | A318, A319, A320, A321 | Fuselage - Lateral Window Frame Upper Fastener Holes - Inspection |
| 2020-0018 | 2020-02-04 | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG | RB211 TRENT 900 | Engine Fuel & Control - Hydro-mechanical Metering Units - Removal from Service |
| BR-2020-01-02 | 2020-01-31 | EMBRAER | ERJ-170, ERJ-190 | Nacelles / Pylons - Engine Inboard and Outboard Pylon Lower Link Lugs - Inspection / Repair |
| US-2020-01-18 | 2020-01-31 | BOEING | 757 | Time Limits / Maintenance Checks - Airworthiness Limitations Instructions - Principal Structural Elements - Inspections / Maintenance or Inspection Program Revision |
| 2020-0017 | 2020-01-30 | WSK PZL - SWIDNIK S.A. | PZL W-3A | Equipment / Furnishings - Hoist Assembly - Inspection |
| 2020-0016 | 2020-01-30 | AIRBUS | A380 | Pneumatic - Engine Bleed Air Supply System High Pressure Valves - Modification / Replacement |
| CF-2019-33R1 | 2020-01-30 | BOMBARDIER | BD-700 | Landing Gear - Trailing Arm Assembly Axle Bore Corrosion |
| 2020-0011 | 2020-01-30 | LEONARDO S.p.A. HELICOPTERS | AB139/AW139 | [Correction] Main Rotor Drive - Main Gearbox Bearing Lock Nut - Replacement |
| 2020-0014 | 2020-01-29 | DASSAULT AVIATION | Falcon 7X | Enhanced Avionics System - Software Check |
| 2020-0013 | 2020-01-29 | AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND, LEONARDO S.p.A. HELICOPTERS, WSK PZL - SWIDNIK S.A. | EC175, SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB-BK 117, AB139/AW139, AB204/AB205, AB212/AB412, AS-61, AW169, AW189, PZL W-3A | Fire Protection - Hand-held Fire Extinguishers - Replacement |
| 2020-0012 | 2020-01-29 | AIRBUS | A380 | Doors - Auxiliary Wing Landing Gear Doors - Inspection |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|-------------------------------------|----------------|---|
| 2020-0010R1 | 2020-01-29 | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG | TRENT 1000 | Engine - De-Pairing Limitation |
| 2020-0015 | 2020-01-29 | AIRBUS HELICOPTERS | EC175 | Fuel - Roll-over Valves - Replacement |
| US-2019-23-16 | 2020-01-29 | BOEING | 737 | Wings - Left and Right Upper Wing Skin - Inspection |
| US-2019-25-20 | 2020-01-28 | LOCKHEED MARTIN CORPORATION | 382 (Hercules) | Flight Controls - Elevator Booster Actuator - Inspections |