



Publ. number	Issue Date	TC Holder	Type	Subject
US-2020-07-51	2020-03-22	INTERNATIONAL AERO ENGINES AG	V2500-()5	High Pressure Turbine 1st-Stage Disks - Removal from Service
2020-0065	2020-03-20	LEONARDO S.p.A. HELICOPTERS	A109/A119	Main Rotor - Blades - Inspection
US-2020-05-28	2020-03-20	INTERNATIONAL AERO ENGINES LLC	PW1100 / PW1400	Engine - Main Gearbox Assembly and Electronic Engine Control Software - Removal / Installation
US-2020-04-19	2020-03-19	BOEING	777	Auto Flight - Mode Control Panel - Replacement
US-2020-05-12	2020-03-19	GULFSTREAM AEROSPACE CORPORATION	GVII	NOT ADOPTED - EASA DECISION ATTACHED
2020-0064	2020-03-19	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND	AS 350 / EC 130, AS 355, EC 120 B, EC175, SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB-BK 117	Equipment / Furnishings - Emergency Flotation System / Inflation Hoses - Inspection
2020-0063	2020-03-18	SCHEMPP HIRTH FLUGZEUGBAU	Ventus Powered Sailplanes, Ventus Sailplanes	Flight Controls - Flaperon Control - Inspection / Replacement
CF-2020-05	2020-03-17	VIKING AIR LTD	DHC-6 (Twin Otter)	Wings - Cracking and Corrosion of Aileron Internal Structure
2020-0061	2020-03-17	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Windows - Jettisoning System - Modification
2020-0058	2020-03-17	AIRBUS	A380	Equipment / Furnishings - Emergency Locator Transmitter Protection - Modification
2020-0059	2020-03-17	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211-524	Engine - Low Pressure Turbine Stage 1 Discs - Life Reduction
2020-0062-E	2020-03-17	LEONARDO S.p.A. HELICOPTERS	AB212/AB412	Tail Rotor - Hub / Blade Assembly - Replacement
CF-2020-06	2020-03-16	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Standard Practices/Structures - Introduction of Barrel Nut Inspections
2020-0060	2020-03-16	AIRBUS	A350	Exhaust - Pressure Relief Latch Access Doors - Modification
CF-2020-04	2020-03-16	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel - Accumulation of Electrostatic Charge Inside the Fuel Tank During Refueling
2020-0057	2020-03-13	AIRBUS HELICOPTERS	EC175	Rotorcraft Flight Manual - Supplements / One Engine Inoperative Performance Limitations - Amendment
2020-0056	2020-03-13	SOLO KLEINMOTOREN GmbH	2625	Engine Fuel & Control - Engine Control Unit - Software Update



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0051	2020-03-11	AIRBUS	A300-600	Fuselage - Upper Frame Feet Fittings - Modification
2020-0050	2020-03-11	AIRBUS	A300-600	[Correction] Fuselage - Main Deck Cargo Crossbeams - Inspection / Repair
2020-0054	2020-03-11	AIRBUS	A330	Flight Controls - Spoiler Servo Control / Hydraulic Locking Function - Operational Test
2020-0055	2020-03-11	CFM INTERNATIONAL	LEAP-1B	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Implementation
2020-0053	2020-03-10	AIRBUS	A320, A321	Nacelles / Pylons - Engine Pylon Nose Fire Seals - Inspection / Replacement
2020-0052	2020-03-10	AIRBUS	A319	Fuselage - Satellite Communications Antenna Doubler - Inspection / Replacement
US-2020-04-11	2020-03-10	BOEING	747	Fuselage - Upper Skin Lap Splice - Inspection
2020-0049	2020-03-09	AIRBUS HELICOPTERS	EC175	Fuel System - Fuel Tank - Inspection/Replacement
CF-2020-03	2020-03-09	BOMBARDIER	CL-600 (Regional Jet)	Fuel System - Primary Ejector Fuel Feed Flexible Hoses Inner Tube Cracking